



Temple Dinsley
Materials as Existing and as Proposed

<u>Materials as Existing</u>	<u>Materials as Proposed</u>
<u>Pavilion</u> <u>Roof</u> - Peg tile with bonnet hips. Flat Roof section presumed to be lead originally. <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – N/A <u>Rainwater Goods</u> - plastic <u>Boundary Treatments</u> – Brick wall adjoining <u>External Paths</u> – Concrete / brick <u>Ventilation Bricks</u> – N/A <u>Ventilation Cows</u> – N/A	<u>Roof</u> - Peg tile with bonnet hips. Flat Roof section presumed to be lead originally. <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – N/A <u>Rainwater Goods</u> – painted cast metal <u>Boundary Treatments</u> – Brick wall adjoining <u>External Paths</u> – Brick / stone <u>Ventilation Bricks</u> – N/A <u>Ventilation Cows</u> – N/A
<u>West Spur</u> <u>Art Block</u> <u>Roof</u> – Felt roof laid to fall. <u>Walls</u> – Red brick and red hanging tiles <u>Windows</u> – Painted metal <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> - Lino <u>Rainwater Goods</u> - plastic <u>Boundary Treatments</u> – red brick wall	<u>West Spur</u> <u>Art Block</u> <u>Roof</u> – Sedum roof laid to fall. <u>Walls</u> – Red brick and red hanging tiles <u>Windows</u> – Painted metal <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – Timber boards <u>Rainwater Goods</u> – painted cast metal <u>Boundary Treatments</u> – red brick wall

<u>External Paths</u> – Stone, brick, concrete <u>Ventilation Bricks</u> – tile, terracotta <u>Ventilation Cowels</u> – N/A <u>North Extension to West Wing</u> <u>Roof</u> – Felt roof laid to fall. <u>Walls</u> - Red brick <u>Windows</u> - Painted timber <u>Rooflights</u> - NA <u>Doors</u> - Painted timber <u>Floor</u> - NA <u>Rainwater Goods</u> - painted cast metal <u>Boundary Treatments</u> - NA <u>External Paths</u> - Stone <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA	<u>External Paths</u> – Stone, brick, concrete <u>Ventilation Bricks</u> – tile, terracotta <u>Ventilation Cowels</u> – N/A <u>North Extension to West Wing</u> <u>Roof</u> - Sedum roof laid to fall. <u>Walls</u> - Red brick <u>Windows</u> - Painted timber <u>Rooflights</u> - NA <u>Doors</u> - Painted timber <u>Floor</u> - NA <u>Rainwater Goods</u> - painted cast metal <u>Boundary Treatments</u> - NA <u>External Paths</u> - Stone <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA
<u>East and West Wing</u> <u>Roof</u> – Red peg tile <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – Timber, brick, concrete <u>Rainwater Goods</u> – lead, painted metal, plastic	<u>Roof</u> – Red peg tile <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – Timber, brick, concrete / limecrete <u>Rainwater Goods</u> – lead, painted metal,

<u>Boundary Treatments</u> – Brick, stone capping, terracotta <u>External Paths</u> – stone, brock <u>Ventilation Bricks</u> - tile <u>Ventilation Cows</u> – N/A	<u>Boundary Treatments</u> – Brick, stone capping, terracotta <u>External Paths</u> – stone, brock <u>Ventilation Bricks</u> - tile <u>Ventilation Cows</u> – N/A
<u>Old House</u> <u>Roof</u> - Peg tile with lead parapet gutters, copper, lead. <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – timber, stone, brick <u>Rainwater Goods</u> - lead <u>Boundary Treatments</u> – red brick walls and iron railings <u>External Paths</u> – stone and brick <u>Ventilation Bricks</u> – clay tile <u>Ventilation Cowels</u> – N/A	<u>Roof</u> - Peg tile with lead parapet gutters, copper, lead <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber <u>Floor</u> – timber, stone, brick <u>Rainwater Goods</u> - lead <u>Boundary Treatments</u> – red brick walls and iron railings <u>External Paths</u> – stone and brick <u>Ventilation Bricks</u> – clay tile <u>Ventilation Cowels</u> – N/A
<u>East Annexe</u> <u>Roof</u> - Peg tile with bonnet hips. Flat Roof section presumed to be lead originally. <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A	<u>Roof</u> - Peg tile with bonnet hips. Flat Roof section presumed to be lead originally. <u>Walls</u> – Red brick <u>Windows</u> – Painted timber <u>Rooflights</u> – N/A <u>Doors</u> – Painted timber

<u>Doors</u> – Painted timber <u>Floor</u> – timber, stone, brick <u>Rainwater Goods</u> - lead <u>Boundary Treatments</u> – red brick walls and iron railings <u>External Paths</u> – stone and brick <u>Ventilation Bricks</u> – clay tile <u>Ventilation Cows</u> – N/A	<u>Floor</u> – timber, stone, brick <u>Rainwater Goods</u> - lead <u>Boundary Treatments</u> – red brick walls and iron railings <u>External Paths</u> – stone and brick <u>Ventilation Bricks</u> – clay tile <u>Ventilation Cows</u> – N/A
<u>Teaching Block</u> <u>Roof</u> – Red plain tile, felt <u>Walls</u> – Red brick <u>Windows</u> – painted timber, painted metal <u>Rooflights</u> -N/A <u>Doors</u> – Painted timber <u>Floor</u> – Timber, concrete <u>Rainwater Goods</u> - plastic <u>Boundary Treatments</u> – Red brick <u>External Paths</u> - Concrete <u>Ventilation Bricks</u> - clay tile <u>Ventilation Cows</u> – N/A	<u>Roof</u> – Red plain tile, felt <u>Walls</u> – Red brick <u>Windows</u> – painted timber, painted metal <u>Rooflights</u> -N/A <u>Doors</u> – Painted timber <u>Floor</u> – Timber, concrete <u>Rainwater Goods</u> - plastic <u>Boundary Treatments</u> – Red brick <u>External Paths</u> – Concrete, stone, brick <u>Ventilation Bricks</u> - clay tile <u>Ventilation Cows</u> – N/A
<u>Science Block (To be demolished)</u> <u>Roof</u> – Tiled roof. <u>Walls</u> – Vertical tiles, English-bond multi-stack face brickwork.	<u>Edwin</u> <u>Roof</u> –Clay peg-tile roof supported by lightweight timber frames. <u>Walls</u> – Red brick wall.

<u>Windows</u> – Double glazed treated timber window with slim profile glazing bars surface bonded to glass inside & out, with space bar within sealed unit, red brick quoins, timber cill. <u>Rooflights</u> – None. <u>Doors</u> – Painted timber <u>Floor</u> – NA <u>Rainwater Goods</u> - PVC <u>Boundary Treatments</u> - NA <u>External Paths</u> - concrete <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA	<u>Windows</u> – Dark-grey aluminium-clad-timber triple-glazed window. <u>Rooflights</u> – Dark-grey aluminium-clad-timber triple-glazed roof windows; Triple-glazed glass formed dormers. <u>Doors</u> - Dark-grey aluminium-clad-timber triple-glazed doors. <u>Rainwater Goods</u> - Dark metal rainwater goods. <u>Boundary Treatments</u> – Willow fencing, metal estate fencing. <u>External Paths</u> – permeable bound gravel areas, planted with multi-stem shrubs
<u>Piggery</u> <u>Roof</u> - Peg tile with bonnet hips. <u>Walls</u> – C19 red brickwork <u>Windows</u> – Painted timber casements <u>Doors</u> – Painted boarded door <u>Floor</u> - Earth <u>Rainwater Goods</u> - painted cast metal <u>Boundary Treatments</u> - NA <u>External Paths</u> - NA <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - N	<u>Roof</u> - Peg tile with bonnet hips. <u>Walls</u> – C19 red brickwork <u>Windows</u> - Painted timber casements <u>Doors</u> - Painted boarded door <u>Floor</u> - Earth <u>Rainwater Goods</u> - painted cast metal <u>Boundary Treatments</u> - NA <u>External Paths</u> - NA <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA
<u>Barn 1 (Summerhouse)</u> <u>Roof</u> – Felt roof <u>Walls</u> – Weatherboard	

<u>Windows</u> – LC20 Timber Casements <u>Rooflights</u> – NA <u>Doors</u> - LC20 Timber Boarded Doors <u>Floor</u> - LC20 Timber Boarded Floor <u>Rainwater Goods</u> - plastic <u>Boundary Treatments</u> - NA <u>External Paths</u> - NA <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA	
<u>Pumping Station (Pump House)</u> <u>Roof</u> - Peg tile with bonnet hips. Flat Roof section presumed to be lead originally. <u>Walls</u> – Red Bricks laid Flemish Bond with Queen Closers. Semi-circular Arch Details. <u>Windows</u> -Painted timber casements. Louvres inset in a painted timber frames within some arches. <u>Rooflights</u> – N/A <u>Doors</u> – Painted boarded doors. <u>Floor</u> – Earth floors. <u>Rainwater Goods</u> – Missing painted cast iron. <u>Boundary Treatments</u> – Post and rail fencing.	<u>Roof</u> - Peg tile with bonnet hips. New Extension to have a peg tile roof. <u>Walls</u> – Red Bricks laid Flemish Bond with Queen Closers. Semi-circular Arch Details. New Extension to have small sections of silvered weatherboard. <u>Windows</u> – Painted timber casements to be repaired. Any new casements to have painted timber frames and slim double glazing. <u>Rooflights</u> – Conservation rooflights with dark grey frames and minimal projection. <u>Doors</u> – Painted boarded doors. New doors a mixture of painted boarded doors, painted timber frame doors with glazing and aluminium frame in dark grey to the Extension. <u>Floor</u> – Insulated slabs with breather perimeters where required. <u>Rainwater Goods</u> – New heritage style painted aluminium half round gutters with rafter brackets

<u>External Paths</u> – N/A <u>Ventilation Bricks</u> – N/A <u>Ventilation Cowels</u> – N/A	<u>Boundary Treatments</u> - Painted Estate Rail Fencing to define immediate boundary. Post and rail fencing for garden and driveway. <u>External Paths</u> – Gravel finish. <u>Ventilation Bricks</u> - Painted Cast iron bricks <u>Ventilation Cowels</u> – Painted Cast iron conservation cowel.
<u>Barn 2 (Tank House)</u> <u>Roof</u> - Peg tile with clay half round ridge tiles. <u>Walls</u> – black timber weatherboard <u>Windows</u> – painted timber <u>Rooflights</u> -NA <u>Doors</u> – Painted timber <u>Floor</u> – earth /concrete <u>Rainwater Goods</u> - none <u>Boundary Treatments</u> – post and wire <u>External Paths</u> – N/A <u>Ventilation Bricks</u> - N/A <u>Ventilation Cowels</u> - N/A	<u>Roof</u> - Peg tile with clay half round ridge tiles. <u>Walls</u> – black timber weatherboard <u>Windows</u> – painted timber <u>Rooflights</u> -NA <u>Doors</u> – Painted timber <u>Floor</u> – earth /concrete <u>Rainwater Goods</u> – painted cast metal <u>Boundary Treatments</u> – post and wire <u>External Paths</u> – N/A <u>Ventilation Bricks</u> - N/A <u>Ventilation Cowels</u> - N/A
<u>Belvedere</u> <u>Roof</u> - Peg tile with bonnet hips. <u>Walls</u> – Red Brick <u>Windows</u> – Painted timber sashes <u>Doors</u> -Painted timber <u>Floor</u> – Viewing floor is stone with an inlaid floor brick pattern. Lower floor is and earth floor.	<u>Roof</u> - Peg tile with bonnet hips. <u>Walls</u> – Red Brick <u>Windows</u> – Painted timber sashed <u>Doors</u> -painted door <u>Floor</u> - Viewing floor is stone with an inlaid floor brick pattern. Lower floor is and earth floor.

<u>Rainwater Goods</u> – Cast iron <u>Boundary Treatments</u> - <u>External Paths</u> – Stone steps with red brick risers. <u>Ventilation Bricks</u> – N/A <u>Ventilation Cowels</u> – N/A	<u>Rainwater Goods</u> – Cast iron <u>Boundary Treatments</u> – Estate fencing <u>External Paths</u> - Stone steps with red brick risers. <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA
<u>Ice House</u> <u>Roof</u> – Tree roots with brick vaulted arches. <u>Walls</u> – Tree roots with brick underground retaining walls. <u>Doors</u> – Wrought iron gate. Poor condition. <u>Floor</u> - Earth <u>Rainwater Goods</u> – N/A <u>Boundary Treatments</u> - N/A <u>External Paths</u> - N/A	<u>Roof</u> - Tree roots with brick vaulted arches. <u>Walls</u> - Tree roots with brick underground retaining walls. <u>Doors</u> – Wrought iron gate. Poor condition. <u>Floor</u> - Earth <u>Rainwater Goods</u> – N/A <u>Boundary Treatments</u> - Estate fencing <u>External Paths</u> – See East Park landscape
<u>Sports Hall</u> <u>Roof</u> – clay effect pantile (main roof); corrugated sheet metal (external store roof); with PV panels <u>Walls</u> – timber construction, red painted timber planks <u>Windows</u> – Painted timber <u>Rooflights</u> - Painted timber <u>Doors</u> - Painted timber <u>Floor</u> – Timber Spots Hall floor with markings <u>Rainwater Goods</u> - PVC	<u>Violet</u> <u>Roof</u> – Slate roof supported by lightweight timber frames; PV slates (matching) on the roof surface facing west. <u>Walls</u> – Red brick wall. <u>Windows</u> – Dark-grey aluminium-clad-timber triple-glazed window. <u>Rooflights</u> – Dark-grey aluminium-clad-timber triple-glazed roof windows; Triple-glazed glass formed dormers <u>Doors</u> - Dark-grey aluminium-clad-timber triple-glazed doors.

<u>Boundary Treatments</u> - NA <u>External Paths</u> - NA <u>Ventilation Bricks</u> - NA <u>Ventilation Cowels</u> - NA	<u>Rainwater Goods</u> - Dark metal rainwater goods <u>Boundary Treatments</u> – Willow fencing, metal estate fencing. <u>External Paths</u> – permeable bound gravel areas, planted with multi-stem shrubs - Ithel <u>Roof</u> – Slate roof supported by lightweight timber frames, PV slates (matching) on the roof surface facing south. <u>Walls</u> – Red brick walls. <u>Windows</u> – Dark-grey aluminium-clad-timber triple-glazed window. <u>Rooflights</u> - Dark-grey aluminium-clad-timber triple-glazed roof windows. <u>Doors</u> - Dark-grey aluminium-clad-timber triple-glazed doors. <u>Rainwater Goods</u> - Dark metal rainwater goods <u>Boundary Treatments</u> – Willow fencing, metal estate fencing. <u>External Paths</u> – permeable bound gravel areas, planted with multi-stem shrubs - Sadleir <u>Roof</u> – Clay peg tile roof supported by lightweight timber frames. <u>Walls</u> – Red brick walls; face and cheeks of the two south facing mid-strays clad in Corten steel. <u>Windows</u> – Dark-grey aluminium-clad-timber triple-glazed window. <u>Rooflights</u> -
--	---

	<u>Doors</u> - Dark-grey aluminium-clad-timber triple-glazed doors. <u>Rainwater Goods</u> - Dark metal rainwater goods <u>Boundary Treatments</u> – Willow fencing, metal estate fencing. <u>External Paths</u> – permeable bound gravel areas, planted with multi-stem shrubs - Templar <u>Roof</u> – Corten or zinc roof supported by lightweight timber frame, with matching PV panels. <u>Walls</u> – Red brick wall. <u>Windows</u> – Dark-grey aluminium-clad-timber triple-glazed window. <u>Rooflights</u> – Dark-grey aluminium-clad-timber triple-glazed roof windows. <u>Doors</u> - Dark-grey aluminium-clad-timber triple-glazed doors <u>Rainwater Goods</u> - Dark metal rainwater goods <u>Boundary Treatments</u> – Willow fencing, metal estate fencing. <u>External Paths</u> – permeable bound gravel areas, planted with multi-stem shrubs
	Summerhouse & Harwood House Carport and Store <u>Structure</u> – Corten steel structure. <u>Cladding</u> – Timber cladding. <u>Doors</u> – Timber doors. <u>Roof</u> – Glass solar panel roofs.

	<u>External Paths</u> – meandering path of loose woodchips of clearing and felling <u>Boundary Treatments</u> – Areas of lawn in less steeply sloping locations, woodland edge wildflowers, eastern part with additional deer fencing
	East Car Park <u>Structure</u> – Timber post structure with timber store walls; Corten steel roof frames with semi-transparent solar PV rainproof canopies. <u>Roof</u> – Semi-transparent solar PV rainproof canopies. <u>Boundary Treatment/ Walled Enclosure</u> – Hornbeam hedge enclosure with trees and shrubs (north-west corner); red brick straight and semicircular garden wall (south and east edge). <u>Floor</u> – Permeable surfaces, different tones of resin-bound aggregate to denote between pedestrian and vehicular areas