

Site name: Land west & South of Reed 1 st School Surveyor: Ian Lorman			Date of survey: 11 th August 2026 Conditions: Clear / dry / still					
Tree number	Species	Height estim (m)	Stem Diam (s) estim (mm) No. of	Crown spread Ave rad estim (m)	Life stage	Observations; structural / physiological condition and any tree work recommendations	Priority / urgency of work	Zone value
Tag 1495	Common Ash	18	650	8	Mature	Crown - Good, Stem - Fair, Basal Area - Good Remove broken hanging branch Large branch snapped and hanging up 5 metres east side	2	1
Tag 1496	Common Ash	20	650	5	Mature	Crown - Good, Stem - Poor, Basal Area - Good Fell Co-dominant leader recently snapped out at 5 metres on south side leaving gaping wound deep into the centre of the trunk that equals or exceeds 50% of the circumference of the trunk. Tree is likely to snap off at this point, especially when decay sets in, if not before	1	1
Tag 1497	Common Ash	20	700	6	Mature	Crown - Fair, Stem - Fair, Basal Area - Good Remove major dead wood Moderate dead wood in east side partially overhanging school field	2	1
Tag 1498	Common Ash	20	700	8	Mature	Crown - Fair, Stem - Good, Basal Area - Good Remove faulted/rotten lower branch on north side overhanging school field Massive live lower branch on north side at 6 metres with advanced decay at base overhanging school playing field	1	1
Tag 1499	Norway Maple	15	600	5	Mature	Crown - Dead, Stem - Dead, Basal Area - Dead Fell Dead and rotten	1	1
Group G1	Woodland belt comprising Common Ash Norway Maple Oak Field Maple Hawthorn	Up to 200	Up to 700	N/A	Mature	All trees inspected. Those trees listed above that require attention have been marked using a numbered aluminium tag and plotted using GP for ease of location by tree surgery contractor	N/A	1