

Fears End, Sandon, Buntingford, Herts SG9 0QZ




Registered in England. Registration No. 9392208.

Registered Office: Building 3, North London Business Park, Oakleigh Road South, New Southgate, England, N11 1GN

Class Q Barn Survey and Structural Assessment Report

Document Control Sheet

Project Name:	Barn at Fears End, Sandon, Buntingford, Herts SG9 0QZ
Client:	Rosemary Campbell
Project Reference:	7417
Report Title:	Class Q Barn Survey and Structural Assessment
Document Reference:	Version 1.1

	Name	Position	Signature	Date
	Written by:- Michael Brace IEng IMIStructE	Director		08 May 2024
	Checked by:- Harry Brace MEng	Senior Engineer		08 May 2024
For and on behalf of MBA Structures Ltd				

Disclaimer

The copyright in this report prepared by MBA Structures Ltd Ltd is owned by them and no such report, plan or document may be reproduced, published or adapted without their written consent. Complete copies of this report may however be made and distributed by the Client in dealing with matters related to the brief.

The information given in this report is solely for the use of the Client noted above. MBA Structures Ltd can accept no responsibility or liability to any third party. The benefit of this report is not transferable to any third party except with the written agreement of the original Client and of MBA Structures Ltd. An extra fee will be payable for such a transfer.

Contents

1	Introduction.....	1
2	Site Appraisal.....	3
3	Description	4
4	Observations.....	6
5	Conclusions	8

Appendix

Appendix A: Photographs

1 Introduction

1.1 MBA Structures Ltd. are instructed to undertake a visual inspection of a detached barn at Fears End, Sandon, Buntingford, Herts SG9 0QZ . It is proposed that the existing structure be renovated for conversion into residential use. We are instructed to report upon the structural condition of the shed and advise upon its suitability for conversion to residential use in connection with a proposed prior approval application. Our inspection and report is therefore limited to consideration of this aspect only.

1.2 We understand that Part 3 Class Q.1(i) of the General Permitted Development Order (hereafter referenced PDO) restricts building operations pursuant to Class Q to:

(i) the installation or replacement of -

(aa) windows, doors, roofs or external walls, or

(bb) water, drainage, electricity, gas or other services,

to the extent reasonably necessary for the building to function as a dwellinghouse; and

(ii) partial demolition to the extent reasonably necessary to carry out building operations allowed by para. Q.1(i)(i), above.

1.3 Further guidance on the extent of building works allowed when changing to residential use is provided in the National Planning Policy Guidance (NPPG) where at para. 105 it states:

“Building works are allowed under the change to residential use. The permitted development right under Class Q assumes that the agricultural building is capable of functioning as a dwelling. However, it recognises that for a building to function as a dwelling some building operations which would affect the appearance of the building, which would otherwise require planning permission, should be permitted. This right allows for the installation or replacement of windows, doors, roofs, external walls, water, drainage, electricity, gas or other services to the extent reasonably necessary for the building to function as a dwellinghouse; and partial demolition to the extent reasonably necessary to carry out these building operations.

It is not the intention of the permitted development right to include the construction of new structural elements for the building. Therefore it is only where the existing building is structurally strong enough to take the loading which comes with the external works to provide for residential use that the building would be considered to have the permitted development right.”

- 1.4 It is the intention of this report to demonstrate that the proposed residential conversion may be executed in compliance with the terms of the GPDO where appropriate.
- 1.5 We have not inspected woodwork or any other areas of the structure that are covered, unexposed or otherwise inaccessible. We are therefore unable to confirm that any such areas of the building are free from defect. Given the nature of the structure, however, this has not precluded a comprehensive assessment of its structural condition and suitability for conversion.
- 1.6 All observations are made using compass point references to align the building, then handings related to the designated front elevation thereafter, where appropriate.
- 1.7 It is important to note that this report does not constitute a comprehensive Building Survey, neither does it constitute a full Structural Survey. This is a report generated from a visual inspection of the premises in response to a specific matter for consideration and no invasive investigations or opening up has been undertaken nor is deemed necessary.
- 1.8 The weather at the time of inspection was overcast and cold with light rain.
- 1.9 The inspection of the barn floor was inhibited by a quantity of storage. This did not, however, prevent a meaningful inspection sufficient to draw representative conclusions on the overall condition of the structure.
- 1.10 All quoted dimensions and sections sizes are approximate unless specifically noted and should not be relied upon.

2 Site Appraisal

Location

- 2.1 The subject barn is located on land at Fears End, Sandon, Buntingford, Herts SG9 0QZ as shown outlined red in Figure 2.1 below.



Figure 2.1: Site Location Plan

3 Description

- 3.1 The subject barn is approximately 1.0 km north east of the village of Sandon, which itself is located around 6 km north-west of Buntingford and 8 km south-east of Royston. The barn lies to the east side of an un-named lane between Sandon and Kelshall, and occupies a site which is generally level. The surrounding land is generally laid to arable farmland, although there are small wooded areas located immediately to the south and east. Further residential properties, Fears End and Fallowfields, are immediately to the north of the barn.
- 3.2 The barn under consideration appears to have been constructed some 40 years on account of its form and the materials used, and appears to have been primarily used as storage and workshop, currently used for storage.
- 3.3 The barn comprises a long structure comprising timber walls, with a timber pitched roof over.
- 3.4 The building has a span of around 5.3m, a length of around 9m with an internal ceiling height of 2.6m.
- 3.5 The roof is clad with profiled metal sheeting, supported on an assumed timber truss that is fully concealed internally by a boarded ceiling.
- 3.6 Timber framed studwork forms the walls, internally lined with horizontal timber cladding externally.
- 3.7 The floor of the shed is ground bearing concrete slab.

- 3.9 The building is provided with eaves level steel rainwater guttering to each side together with corresponding downpipes which are assumed to ultimately discharge to soakaways.
- 3.10 The foundations are likely to comprise shallow mass concrete strip footings which, given the age of the building are likely to bear at a depth of around 500mm below the prevailing ground level.
- 3.11 Reference to the online mapping of the British Geological Survey (BGS) suggests the barn is situated on prevailing ground conditions, comprising superficial deposits of Lowestoft Formation Diamicton (Boulder Clay), underlain by Lewes Nodular and Seaford Chalk at depth.
- 3.12 Salient photographs of the shed and its surroundings are included as Appendix A.

4 Observations

- 4.1 The barn is in a generally good state of repair.
- 4.2 Externally, the roof presents a reasonably satisfactory alignment with no evidence of significant deflection or distortion noted, suggesting the trusses are largely performing adequately. The roof sheeting is largely intact and robustly fixed to the underlying structural elements.
- 4.3 In other respects, the roof framing appear generally in a adequate condition.
- 4.4 The rainwater goods are generally in good condition.
- 4.5 The floor slab presents in a generally good condition where visible, being robustly free from significant cracking or hollow soundings where tested. Some uneven patch repairs are visible. This work is required irrespective of any conversion works to maintain the building in a serviceable condition.

5 Conclusions

- 5.1 On the basis of our inspection, we are satisfied that the shed represents a viable proposition for conversion to residential use without the need for structural intervention in contravention of the Class Q restrictions.
- 5.2 The floor slab appears to be in a sound condition, and will be subject to a reduction in imposed load within a residential dwelling, as currently there is a great deal of heavy storage. The existing floor slab should therefore be suitable to form a sound base from which to raise partitions and install insulation and floor finishes appropriate to a domestic floor.
- 5.3 The existing foundations appear generally suitable to sustain the loadings currently imposed by the structure, with no evidence to suggest significant past foundation settlement.
- 5.4 The proposals to convert the building to habitable use will involve the addition of little appreciable additional load and there is, as a consequence, no reason to believe the foundation system should not continue to perform in an acceptable manner.
- 5.5 Whilst the existing foundations are possibly a little shallow in respect of current standards, they have clearly proved adequate generally over the years since construction of the barn took place. The prevailing ground conditions are unlikely to give rise to significant or detrimental volume change with variation in moisture content, which can give rise to movement in relatively shallow founded buildings, provided no significant vegetation is planted in close proximity to the building in the future.
- 5.6 The exiting roof structure is generally performing satisfactorily and is configured to provide support to roof sheeting panels.
- 5.7 The structural configuration will not permit the use of a replacement traditional tiled or slated roof covering, which would incur additional and excessive load. The roof replacement must therefore comprise some form of sheeting panel system of similar form to that currently employed but utilising modern materials imposing a similar, or potentially lesser load.

- 5.8 In summary, the overall condition of the barn structure, together with its overall performance to date, lead us to believe there is no substantive reason why it cannot be successfully converted to residential use without recourse to structural intervention, other than that which would be required to maintain the integrity of the structure in its current form.
- 5.9 With this in mind, we consider the existing building described herein is in principle structurally strong enough to sustain the loadings from the building operations reasonably necessary to facilitate its conversion to residential use.

Appendix A: Photographs



Internal arrangement.



Concrete floor slab.