



- Existing front elevation
- The mismatched window styles between the ground floor and 1st floor in front elevation nor keeping with heritage conservation.
 - Existing windows are rotten and beyond economical repair
 - Windows let water in the property and cause damp problems
 - Property very cold in winter and doesnt keep heat in

