

## **Youngloves Farmhouse**

### **Window Pentice Detail**

Existing on the South elevation – Tile pentice with rough cast render



Proposed (Existing on East and North) – Timber Pentice detail



### Plinth detail

Existing on the South elevation – concrete plinth with rough cast render



Proposed (Existing on East and North) – Brick Plinth

