

Photographic Survey - Windows

**Old Sextons
Sandon
Buntingford
Hertfordshire
SG9 0QX**

Conservation Officer Site Visit – 17 September 2025

W1



W2



W3



W4



W5



W6



W7



W8



W9



W10



W11



W12



W13



W14



Unnumbered



W15



W16



W17



W18



Front (south)



Front (south)



Side (west)



Rear (north)



Rear (north)



Side (east)



Drafting error to rear (north) elevation – W8 (quarter-pane not 6-pane)

Area of soil cut back to an incline and french drain provided to external perimeter of dwelling at bottom of sloped area, to suit site levels. French drain to be set approx 150mm below slab level.

Trial hole exploration required to confirm condition/extent of buried structure.

Structural Engineer to confirm and all agreements to be secured with land owner(s) prior to commencement of works.

100mm dia perforated pipe surrounded in free flowing material wrapped in a geotextile and topped with large pebbles, edge planning of ornamental flowers to be agreed with all parties.

Strip existing
only. Check
before inst
permeable s
New timber
battens as s
existing roof
new to matc

