

Window 1.
Front elevation.
Ground floor, right hand side.



This timber single glazed sash window is a relatively recent replacement. When compared to the same window at No 22 Horn Hill this window has been replaced as it is four courses of brickwork shorter. Non original bricks with sand and cement mortar, rather than traditional lime mortar, has been used to infill below this window. The window itself has been brought forward level with the face of the brickwork - probably to allow secondary glazing to be fitted neatly internally. It would appear that apart from the bottom courses of brickwork being altered the reveals and brick lintel are original.

Window 4.
Front Elevation.
First floor left hand side.



This timber single glazed sash window is a relatively recent replacement. When compared to the same window at No 22 Horn Hill this window has been replaced as this window is four courses of brickwork shorter. Non original bricks with sand and cement mortar, rather than traditional lime mortar has been used to infill below this window and the window itself has been brought forward level with the face of the brickwork - probably to allow secondary glazing to be fitted neatly internally. It would appear that apart from the bottom courses of brickwork being altered the reveals and brick lintel are original. The cast iron canted railing appears to be original however it has been repositioned from it's original location.

Window 2.
Front elevation.
Ground floor, left hand side.



This timber single glazed sash window is a relatively recent replacement. When compared to the same window at No 22 Horn Hill this window has been replaced as this window is four courses of brickwork shorter. Non original bricks with sand and cement mortar, rather than traditional lime mortar has been used to infill below this window and the window itself has been brought forward to the face of the brickwork - probably to allow secondary glazing to be fitted neatly internally. It would appear that apart from the bottom courses of brickwork being altered the reveals and brick lintel are original.



Window 5.
Side elevation.
Ground floor

This timber single glazed sash window is a relatively recent replacement. It may have replaced a historic door with brickwork infilled below but this is not certain. There is no stone sill, simply a modern tile sill. This window has been brought forward with architrave style beading to infill between the window and the brickwork. It is likely that the brick lintel above is not the original. The pointing adjacent this window is generally modern sand and cement, rather than traditional lime mortar. The brickwork immediately above the window appears to have dropped slightly with cracks opening in the mortar joints above

Window 3.
Front Elevation.
First floor right hand side.



This timber single glazed sash window is a relatively recent replacement. When compared to the same window at No 22 Horn Hill this window has been replaced as this window is four courses of brickwork shorter. Non original bricks with sand and cement mortar, rather than traditional lime mortar has been used to infill below this window and the window itself has been brought forward level to the face of the brickwork - probably to allow secondary glazing to be fitted neatly internally. It would appear that apart from the bottom courses of brickwork being altered the reveals and brick lintel are original. The cast iron railing appears to be the original however it has been repositioned from it's original location.

EXISTING WINDOWS 1, 2, 3, 4 & 5

Address.
18, Horn Hill
Whitwell
Herts.
SG4 8AS

Ref No.
A 02

Title.
Existing
Windows 1, 2,
3, 4 & 5

Date.
17th April 2025