

Marlborough Close Weston



Settle Tree plotter data mapping



T1

TREE DETAILS - 1

CLOSEVIEW PHOTOS

VTA

BS5837

OBSERVATIONS

MISC

CAVAT

BBVJV

ATLAS WORKPLACE ADDITIONAL DATA

WORK RECORDS

HISTORY

Observation Comments	Low branches overhanging parking spaces.
Root/Base Observations	Strimmer/Mower Damage
Trunk Observations	No Visible Issues or Defects
Crown Observations	Low Branches
Crown Diseases	No Visible Issues or Defects
Works Required	Yes
Pests, Pathogens & Diseases	None Observed
Ecological Considerations	None Observed
Poisonous?	
Ash Dieback Survey	
Crown Light Exposure	Crown is fully exposed to light.



CLOSE

VIEW PHOTOS

VTA	BS5837	OBSERVATIONS	MISC	CAVAT	BBVJV	ATLAS WORKPLACE ADDITIONAL DATA		WORK RECORDS	HISTORY
		Observation Comments							
						Stem epicormic shoots encroaching over footway.			
		Root/Base Observations				No Visible Issues or Defects			
		Trunk Observations				Epicormic growth			
		Crown Observations				None Significant			
		Crown Diseases				No Visible Issues or Defects			
		Works Required				Yes			
		Pests, Pathogens & Diseases				None Observed			
		Ecological Considerations				None Observed			
		Poisonous?				Fruit are ornamental - not to be eaten			
		Ash Dieback Survey							
		Crown Light Exposure				Crown is fully exposed to light.			

