

Replace all existing
Fascias and Gutters to
Antracite Grey Fascias
and Galvanised Steel
Guttering

Remove Existing
Leaded Windows
and replace with
Light Grey
Windows Frames

