



Rear windows 11-13

Bottom sash has been replaced
& with different beading

Bottom sash written and
has lost its section shape



Side window no. 10

C:
Cracked glazing

N:
Replacement glazing

