N.H.D.C.
09 APR 2018

HERITAGE STATEMENT

The property is a grade 2 listed property enjoying multi-pane windows The dormer window to the front elevation has suffered rot which is beyond repair. It is proposed to replace the 2no flush casements for identical hardwood timber casements painted white to match the existing. As another window in the property has been replaced with listed building consent and has benefitted from slimline double-glazed units it is proposed to install these into the new casements. Any areas of rot to the frame will be cut out and replaced with matching timber sections. The glazing bars will be fitted to the surface of the glass to retain their slim feature. Ironmongery will be traditional "monkey tail".