T CHRISTOPHER'S SCHOOL TREE SAFETY INSPECTION & SURVE January 2018

Tree No.	Species	Scientific name	Height (m)	Age	Stems	DBH (mm)	RPA radius (m)	N (m)	E	S	W	First Branch Height (m)	Direction of growth (m)	BS Cat	General Observations	Recommendations	Priority
T1	Beech	*Fagus sylvatica*	9	M	3	580	7.0	4	4	4	4	2.5	NE	B1	Included unions between stems; ivy previously severed; minor bark wounding on main limbs.	None	-
T2	Apple	*Malus spp.*	2.5	M	2	320	3.8	0	2	4	3	0.5	S	B1	Leaning tree from base with corrected crown.	None	-
T3	Apple	*Malus spp.*	2.5	M	1	270	3.2	2	3	2.5	2	1	n/a	B1	None	None	-
T4	Apple	*Malus spp.*	2.5	M	1	200	2.4	1	2	2	1	1.5	S	C1	Significant rotten wound on east side from base to 0.75m; minor dead wood in crown.	Re-inspect tree in 18 months to assess any further decline in condition	4
T5	Apple	*Malus spp.*	3	M	3	325	3.9	2	1	2.5	3	1	S	B1	None	None	-
T6	Apple	*Malus spp.*	2.5	M	1	160	1.9	0.5	2.5	1	0	0.5	E	B1	None	None	-
T7	Apple	*Malus spp.*	3	M	1	200	2.4	1	1.5	2	0	0.75	SE	B1	None	None	-
T8	Apple	*Malus spp.*	2.5	M	2	150	1.8	2	1	1	1	1	NW	B1	None	None	-
T9	Apple	*Malus spp.*	3	M	2	165	2.0	0.5	2	1.5	0.5	1	SE	B1	None	None	-
T10	Apple	*Malus spp.*	3	M	2	260	3.1	1.5	1	2	3	0.75	SW	B1	None	None	-
T11	Apple	*Malus spp.*	2.5	M	2	210	2.5	1	1	2	2	0.5	W	B1	None	None	-
T12	Apple	*Malus spp.*	2.5	M	3	140	1.7	1	1	1.5	0.5	1.5	n/a	C1	One dead stem and bark loss on remaining stems.	Remove dead stem.	3
T13	Apple	*Malus spp.*	2	SM	1	80	1.0	0.5	1	1	1	0.75	S	C1	None	None	-
T14	Apple	*Malus spp.*	2.5	M	2	170	2.0	1	2.5	2	1	0.75	E	B1	Rotten wound on underside of lowest branch and bark loss on upperside of small stem.	None	-
T15	Apple	*Malus spp.*	2	SM	1	75	0.9	1	1	1	0.5	0.75	S	C1	None	None	-
T16	Apple	*Malus spp.*	2.5	SM	1	100	1.2	0	0.5	1	0.5	1	E	C1	None	None	-
T17	Apple	*Malus spp.*	3.5	M	1	350	4.2	3	3	3	2	2	S	A1	Small cavity on NE side with *Auricularia auricula-judae* fungal brackets emerging; no other significant defects recorded	Re-inspect tree in 18 months to assess any further decline in condition	4
T18	Apple	*Malus spp.*	2	SM	1	100	1.2	1	1	1.5	0.5	0.75	N	C1	None	None	-
T19	Birch spp.	*Betula spp.*	7	SM	1	150	1.8	2.5	3	1	2.5	2	W	B1	None	None	-
T20	Silver birch	*Betula pendula*	9	SM	1	210	2.5	1	2	2.5	2.5	2	SW	B1	None	None	-
T21	Silver birch	*Betula pendula*	9	SM	1	130	1.6	1.5	1.5	0.5	1	3.5	N	B1	None	None	-
T22	Silver birch	*Betula pendula*	10	SM	1	165	2.0	1	0.5	2	2	2	W	B1	None	None	-
T23	Silver birch	*Betula pendula*	10	SM	1	160	1.9	2	3	2	2	2	S	B1	None	None	-
T24	Apple	*Malus spp.*	3	M	1	250	3.0	0.5	2	2.5	1	2.5	S	B1	Decay cavity on north side extending from 0.5m to 1.5m and to 50mm depth.	Re-inspect tree in 6 months to assess crown in leaf and any further decline in condition.	2
T25	Hawthorn	*Crataegus monogyna*	3	M	1	190	2.3	3	2.5	2	2	1.75	NE	C1	Major dead wood in centre of crown and small hanging branch at 2m.	Remove all dead wood and hanging branch.	2
T26	Silver birch	*Betula pendula*	14	M	1	440	5.3	3.5	4	4	3	3	W	A1	None	None	-
T27	Hornbeam	*Carpinus betulus*	11	M	1	860	10.3	5	5	4.5	4.5	2	SE	A1	Tree surrounded by rubber crumb surface; minor dead wood in crown; crown close to buildings but not yet touching.	Consider sensitive crown reduction in future to manage spread of crown and weight on limbs to reduce potential for fracture.	4
T28	Swamp cypress	*Taxodium distichum*	9	M	1	480	5.8	2	2.5	3	3	1.5	S	A1	None	None	-
T29	Birch spp.	*Betula spp.*	2	Y	1	30	0.4	0.5	0.5	0.5	0.5	-	-	C1	None	None	-
T30	Cherry spp.	*Prunus spp.*	4	SM	1	160	1.9	2	2	2	2	2	N	B1	None	None	-

T31	Apple	*Malus spp.*	2	SM	1	90	1.1	1	0.5	1	2	1	W	U	Poor condition with dead wood in crown and bark wounding.	Re-inspect tree in 18 months and fell if condition has continued to deteriorate	**4**
T32	Cherry spp.	*Prunus spp.*	4	SM	1	110	1.3	1.5	1	1.5	2	1	SW	C1	None	None	**-**
T33	Crab apple	*Malus sylvestris*	2.5	SM	1	80	1.0	1	1	1	1.5	0.75	S	C1	None	None	**-**
T34	Cherry spp.	*Prunus spp.*	3.5	SM	1	100	1.2	2	1	2	2	1.75	NW	C1	None	None	**-**
T35	Apple	*Malus spp.*	3.5	M	4	252	3.0	1.5	1	2.5	2	0.5	S	B1	None	None	**-**
T36	Apple spp.	*Malus spp.*	4.5	SM	1	90	1.1	1.5	1	1.5	2	1	S	C1	Two small patches of bark wounding on trunk.	None	**-**
T37	Indian bean tree	*Catalpa bignonioides*	6	SM	1	260	3.1	3	2.5	2.5	3	1	S	A1	None	None	**-**
T38	Apple spp. TBC	*Malus spp.*	3	Y	1	60	0.7	0.5	0.5	0.5	0.5	1	N	C1	Trunk has slight lean to SE but corrected in crown.	None	**-**
T39	Unknown - dead	*n/a*	1.75	Y	1	30	0.4	0.5	0.5	0.5	0.5	-	-	U	Dead tree.	Fell tree to ground level.	**2**
T40	Willow spp.	*Salix spp.*	4	Y	1	25	0.3	0.5	0.5	0.5	0.5	1	W	C1	None	None	**-**
T41	Apple spp. TBC	*Malus spp.*	4.5	SM	1	80	1.0	2	2	2	2	2	SW	C1	None	None	**-**
T42	Apple spp. TBC	*Malus spp.*	3	SM	2	30	0.4	0.5	1	1	0.5	-	-	C1	Tree has slight lean to south	None	**-**
T43	Hawthorn	*Crataegus monogyna*	3.5	SM	1	150	1.8	2	2	2	2	1.25	NE	B1	None	None	**-**
T44	Cherry spp.	*Prunus spp.*	2.5	SM	1	90	1.1	1.5	2	2	2	1.5	S	C1	None	None	**-**
T45	Unknown - TBC	*n/a*	2	Y	1	25	0.3	1	0.5	1	1	1	N	C1	None	None	**-**
T46	Hawthorn spp.	*Crataegus spp.*	6	M	1	230	2.8	3	3	3	4	2	N	B1	None	None	**-**
T47	Cherry spp.	*Prunus spp.*	2.5	SM	2	156	1.9	1.5	2.5	3	2	1.75	S	B1	Included union between two stems at 0.75m height.	None	**-**
T48	Apple	*Malus spp.*	3	SM	2	212	2.5	1.5	2	0	1	1.5	SE	C1	Remains of hollow rotten stem on south side of tree; rotten cavity in stem at 2m.	Re-inspect tree in 18 months to assess any further decline in condition	**4**
T49	Apple	*Malus spp.*	3.5	M	2	256	3.1	2	2	1	2	1.25	E	C1	Large wound on south side of tree with decayed remains of two unidentified fungal fruiting bodies; large dead stub in centre of tree; crown previously pruned as with other apples so know immediate requirement for remedial works.	Re-inspect tree in 18 months to assess any further decline in condition.	**4**
T50	Plum	*Prunus domestica*	5	M	1	170	2.0	3	3	2	2	2	N	B1	Some evidence of minor basal decay on south side of tree.	None	**-**
T51	Cherry spp.	*Prunus spp.*	3	Y	1	55	0.7	1	1	1	1	1.75	NW	C1	Bark wounding from ground to approx 0.75m height.	None	**-**
T52	Crab apple	*Malus sylvestris*	2.5	SM	3	56	0.7	1.5	1.5	1	1	-	-	C1	None	None	**-**
T53	Apple TBC	*Malus spp.*	3.5	SM	1	140	1.7	1.5	2	2	1	1.5	S	C1	Stem previously removed at base on west side of tree; small cavity and evidence of possible fungal fruiting body on remaining stem at 0.75m height	None	**-**
T54	Crab apple	*Malus sylvestris*	4	SM	1	120	1.4	1	1.5	1.5	1.5	0.75	E	C1	None	None	**-**
T55	Crab apple	*Malus sylvestris*	2	Y	1	35	0.4	0.5	0.5	0.5	0.5	0.5	N	U	Poor condition - tree feels loose in ground; evidence of basal rot.	Re-inspect tree in 6 months to assess crown in leaf and any further decline in condition.	**2**
T56	Crab apple	*Malus sylvestris*	2.5	Y	1	80	1.0	0.5	0.5	0.5	0.5	1	S	U	Poor condition - tree feels loose in ground; evidence of basal rot.	Re-inspect tree in 6 months to assess crown in leaf and any further decline in condition.	**2**

T57	Crab apple	*Malus sylvestris*	2.5	Y	1	80	1.0	0.5	0.5	0.5	0.5	1	N	U	Poor condition - tree feels loose in ground; evidence of basal rot.	Re-inspect tree in 6 months to assess crown in leaf and any further decline in condition.	**2**
T58	Crab apple	*Malus sylvestris*	2.5	Y	1	70	0.8	0.5	0.5	0.5	0.5	1	E	U	Poor condition - tree feels loose in ground; evidence of basal rot.	Re-inspect tree in 6 months to assess crown in leaf and any further decline in condition.	**2**
T59	Rowan	*Sorbus aucupaira*	2	Y	1	55	0.7	1	0.5	0.5	1	2	E	C1	Minor basal wounding.	None	**-**
T60	Apple	*Malus spp.*	3	M	1	150	1.8	0.5	0	2.5	1.5	2.5	E	C1	Cavity in stem at 0.5m and bark wounding	None	**-**
T61	Rowan	*Sorbus aucupaira*	2.5	Y	1	50	0.6	1	0.5	0.5	0.5	1	S	C1	None	None	**-**
T62	Rowan	*Sorbus aucupaira*	3.5	SM	2	85	1.0	1	1	1	1	1	W	C1	None	None	**-**
T63	Rowan	*Sorbus aucupaira*	3	Y	1	60	0.7	0.5	1	0.5	0.5	1.5	NW	C1	None	None	**-**
T64	Plum	*Prunus domestica*	5	M	1	340	4.1	2.5	2.5	2	2.5	0.5	S	B1	Included unions between stems.	None	**-**
T65	Cotoneaster 'Cornubia'	*Cotoneaster x watereri 'Cornubia'*	3.5	M	8	110	1.3	2	2	3	2	-	-	C1	None	None	**-**
T66	Cotoneaster 'Cornubia'	*Cotoneaster x watereri 'Cornubia'*	3.5	M	6	110	1.3	2.5	2	1	2.5	-	-	C1	None	None	**-**
T67	Ash	*Fraxinus excelsior*	8	SM	1	190	2.3	2	2.5	2	1	2.5	E	C1	Self set tree	None	**-**
T68	Ash	*Fraxinus excelsior*	10	SM	1	250	3.0	2	2	2	1.5	3	E	B1	Adjacent to overhead cable	None	**-**
T69	Field maple	*Acer campestre*	9	SM	1	200	2.4	2	1	2.5	2	3	S	C1	Adjacent to overhead cable	None	**-**
T70	Elder	*Sambucus nigra*	3	M	1	360	4.3	1.5	0.5	0.5	0.5	3	N	C1	Ivy obscuring inspection; very little crown remaining.	Carefully sever ivy at base of tree.	**2**
G71	Cherry, ash, elder x 18	*n/a*	<8	<M	-	-	-	-	-	-	-	-	-	C1	Scrappy group of stems growing between access road and playing field; most cherries in group showing signs of canker and decay; ash trees poorly sited	Suggest clearing group as one operation and replanting area with an avenue of more suitable trees	**3**
T72	Cherry	*Prunus spp.*	7	M	1	600	7.2	4	5	3	5	2.5	W	U	Significant rotten wounds with extensive decay and bark loss around base and extending up into crown; canker in crown and included unions between stems; minor dead wood in crown.	Fell tree	**1**
T73	Unknown broadleaf	*n/a*	4.5	Y	1	80	1.0	1	1	1	1	2	E	C1	None	None	**2**
T74	Hazel	*Corylus avellana*	4	M	3	220	2.6	0.5	0.5	3	3	-	-	C1	Three stems remaining from hazel stool; rubbing wound at 2m height; bark wounding at base.	None	**-**
T75	Hazel	*Corylus avellana*	4	M	4	270	3.2	1	1.5	3.5	3.5	-	-	C1	Bark wounding on stems.	None	**-**
T76	Cherry	*Prunus spp.*	7	M	1	360	4.3	5	4	1	3	3	N	U	Large wound on trunk with bark loss; tree leaning towards and rubbing against shelter	Fell tree	**1**
T77	Pear	*Pyrus spp.*	9	M	1	430	5.2	1.5	2.5	5	2	2.5	E	A1	Trunk leans towards south but corrected in crown; appears to be in normal vitality	None	**-**
T78	Pear	*Pyrus spp.*	9	M	1	420	5.0	2	4	3	1	5	W	A1	Two small wounds on trunk; ivy around base of tree.	None	**-**
T79	Douglas fir	*Pseudotsuga menziesii*	16	M	1	410	4.9	3	3	3	3	5	SE	B1	Ivy around base of tree.	None	**-**
T80	Cherry spp.	*Prunus spp.*	4.5	SM	1	230	2.8	1	2	1	0.5	2	W	U	Tree in poor condition with *Phellinus pomaceus* fungal brackets throughout and dead wood in crown.	Fell tree	**1**
T81	Cherry spp.	*Prunus spp.*	4.5	SM	1	220	2.6	3	2	1	1	3	S	C1	Large wound on south side of tree with bark loss; minor dead wood in crown.	Fell tree	**2**
T82	Cherry spp.	*Prunus spp.*	5	SM	1	250	3.0	4	2	1	4	2.5	N	C1	None	None	**-**

T83	Cherry spp.	*Prunus spp.*	5	M	1		0.0	4	3	4	2	-	-	C1	Ivy restricting inspection.	Carefully sever ivy at base	**2**
T84	Field maple	*Acer campestre*	17	M	2	976	11.7	4	5	6	5	3	W	A1	Very large specimen field maple; Ivy restricting inspection.	Carefully sever ivy at base.	**2**
T85	Oak	*Quercus robur*	15	M	1	800	9.6	5	5.5	4	4.5	3.5	E	B1	Evidence of dieback in top of crown; large spreading lower limbs with little towards top of tree.	Re-inspect tree in 18 months to assess any further decline in condition	**4**
T86	Yew	*Taxus baccata*	5	Y	2	276	3.3	1.5	1.5	1.5	1.5	2	E	B1	None	None	**-**
T87	Cotoneaster spp.	*Cotoneaster spp.*	4	M	5	150	1.8	3	2	2	3	-	-	C1	None	None	**-**
T88	Oak	*Quercus robur*	6	SM	1	260	3.1	3	3	3	2	2.5	E	B1	None	None	**-**
T89	Horse chestnut	*Aesculus hippocastanum*	13	M	1	700	8.4	3	4	4	5	3.5	NW	U	Multiple bark wounds and evidence of decay on trunk; *Polyporus squamosus* fungal brackets emerging from points at 2.5m and 3.5m on sw side; crown previously reduced but showing signs of dieback; poor condition, tree in decline.	Fell tree	**1**
T90	Oak	*Quercus robur*	8	SM	1	500	6.0	6	5	2	6	2	N	B1	Tree growing very close to building; items stuck in bark.	None	**-**
T91	Silver birch	*Betula pendula*	12	M	1	410	4.9	3	3	3	3	2	NE	A1	None	None	**-**
T92	Cherry	*Prunus spp.*	2.5	SM	1	140	1.7	2	2	1	1	1.75	N	C1	*Phellinus pomaceus* fungal bracket at 1.5m; included union.	Re-inspect tree in 18 months to assess any further decline in condition	**4**
T93	Rowan	*Sorbus aucupaira*	7	M	1	200	2.4	3	2	3	2	3	S	B1	None	None	**-**
T94	Norway maple	*Acer platanoides*	5	SM	1	190	2.3	3	2	3	2	2	N	C1	Bark damage to main stem at 3m	None	**-**
T95	Hawthorn	*Crataegus monogyna*	4	SM	1	130	1.6	1	1	2	2	1.5	S	C1	None	None	**-**
T96	Rowan	*Sorbus aucupaira*	5	M	1	160	1.9	2	1	2	1	2	NE	U	Significant crown dieback and fungal brackets in crown; dead wood present throughout.	Fell tree	**1**
T97	Rowan	*Sorbus aucupaira*	3.5	SM	1	130	1.6	1	2	2	2	2	SW	C1	Minor crown dieback on north side of tree	None	**-**
T98	Silver birch	*Betula pendula*	17	M	1	350	4.2	4	4	5	5	4	S	A1	None	None	**-**
T99	Hawthorn	*Crataegus monogyna*	4.5	M	1	250	3.0	1	2	2	3	2	W	B1	Ivy restricting inspection; minor dead wood in crown.	Carefully sever ivy at base.	**2**
T100	Norway maple	*Acer platanoides*	5	SM	1	120	1.4	1	2	2	2	2	S	C1	None	None	**-**
T101	Norway maple	*Acer platanoides*	5.5	SM	1	130	1.6	1	2	2	2	1.5	S	C1	None	None	**-**
T102	Rowan	*Sorbus aucupaira*	5	M	2	205	2.5	3	2	3	4	1	W	C1	Included stem union at 1m in poor condition - rotten cavity present; dead wood in crown.	Reduce stem on car park side to 1.75m height to reduce risk of fracture at included union	**1**
T103	Norway maple	*Acer platanoides*	10	SM	1	250	3.0	1	4	4	4	2.5	S	B1	None	None	**-**
T104	Norway maple	*Acer platanoides*	11	SM	1	240	2.9	2	3	1	4	4	W	B1	None	None	**-**
T105	Birch spp.	*Betula spp.*	6	SM	1	120	1.4	3	2	1	2	2	W	B1	None	None	**-**
T106	Cherry spp.	*Prunus spp.*	5	SM	1	150	1.8	3	4	3	4	2.5	W	B1	None	None	**-**
T107	Birch spp.	*Betula spp.*	6	SM	1	120	1.4	2	2	2	2	2	E	B1	None	None	**-**
T108	Scots pine	*Pinus sylvestris*	17	SM	1	240	2.9	1	1	2	2	8	SW	B1	Heavily ivy clad, restricting inspection.	Carefully sever ivy at base	**2**
T109	Ash	*Fraxinus excelsior*	11	SM	2	235	2.8	0.5	0	6	6	6	W	B1	Partially ivy clad	None	**-**
T110	Ash	*Fraxinus excelsior*	15	SM	1	350	4.2	2	5	6	5	6.5	SW	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T111	Hawthorn	*Crataegus monogyna*	6	M	3	335	4.0	1	2	2	2	-	-	C1	None	Remove sucker growth from base of tree	**3**
T112	Hawthorn	*Crataegus monogyna*	8	M	1	300	3.6	2	2	2	3.5	3	S	U	Significant crown dieback and dead wood in crown; ivy clad stem.	Fell tree	**1**
T113	Hawthorn	*Crataegus monogyna*	6	M	1	320	3.8	3	3	4	4	2	S	C1	Dead wood in crown from previously severed ivy.	None	**2**

T114	Scots pine	*Pinus sylvestris*	10	M	1	470	5.6	3	5	6	3	4.5	W	B1	Top of tree previously removed or failed; remaining large limbs in good vitality although some minor deadwood present and branch just touching building.	Climbing inspection to assess wound at top of tree; while climbing remove any dead wood and prune back limb on building side by 1.5m.	**2**
T115	Lime	*Tilia spp.*	23	M	1	750	9.0	4	7	9	6	5	SE	A1	Minor dieback evident with dead wood present at the tips of some limbs; long spreading limbs across pedestrian areas of school.	Remove sucker growth up to 5m height; reduce and reshape crown to a finished height of 20m and radial spread of approx. 5m.	**2**
T116	Scots pine	*Pinus sylvestris*	20	M	1	380	4.6	6	2	1	4	7	SW	A1	None	None	**-**
T117	Scots pine	*Pinus sylvestris*	13	SM	1	300	3.6	6	1	3	3	7	S	C1	Previously severed ivy still attached to stem; cuts carried out with a chainsaw leaving multiple wounds on stem.	Re-inspect tree in 18 months to assess any further decline in condition as a result of chainsaw wounds.	**4**
T118	Yew	*Taxus baccata*	8	M	4	420	5.0	6	5	2	2	2	S	A1	Included unions between stems	None	**-**
T119	Yew	*Taxus baccata*	5	SM	4	280	3.4	2	2	2	2	2	E	B1	None	None	**-**
T120	Lime	*Tilia spp.*	23	M	1	700	8.4	4	4	5	6	3.5	N	U	Significant basal decay wound on south side of tree extending across entire width of trunk and to 1.25m height; rot appears to extend into roots and *Kretzschmaria deusta* fungal bodies present; crown appears to be in reasonable condition but with some major dead wood present.	Fell tree; alternative would be to consider a heavy crown reduction or pollard, but its location would likely make this unfeasible.	**1**
T121	Yew	*Taxus baccata*	5	SM	1	320	3.8	2	2	1	3	2	W	B1	None	None	**-**
T122	Yew	*Taxus baccata*	6	SM	3	360	4.3	6	1	0	0	2	N	C1	Epicormic shooting from trunk; poor form with stems spreading north.	None	**-**
T123	Yew	*Taxus baccata*	7	M	1	520	6.2	5	1	3	4	3	W	A1	None	None	**-**
T124	Austrian pine	*Pinus nigra*	17	M	1	400	4.8	2	1	2	4	5	W	B1	None	None	**-**
T125	Austrian pine	*Pinus nigra*	21	M	1	540	6.5	7	4	3	6	7	W	A1	None	None	**-**
T126	Contorted hazel	*Corylus avellana contorta*	2.5	M	1	190	2.3	1.5	1	1	1	0.5	N	B1	None	None	**-**
T127	Unknown broadleaf TBC	*n/a*	2.5	Y	1	120	1.4	1	1	2	2	1.5	W	C1	Included union between stems at 1.5m height; poor growing form for a young tree.	None	**-**
T128	Unknown broadleaf TBC	*n/a*	2.5	Y	1	120	1.4	2	2	2	2	2	N	C1	None	None	**-**
T129	Unknown broadleaf TBC	*n/a*	3	Y	1	60	0.7	1	1	1	1	1.75	S	C1	None	None	**-**
T130	Birch spp.	*Betula spp.*	8	SM	1	200	2.4	4	4	4	4	2	N	A1	None	None	**-**
T131	Cypress spp.	*Cupressus spp.*	8	M	1	500	6.0	3	3	3	3	-	-	B1	Lower branches cut back on east side for pedestrian access.	None	**-**
T132	Blue spruce	*Picea pungens*	4.5	SM	1	120	1.4	1	1	1	1	2	n/a	C1	Lower branches previously removed; minor dead wood in crown.	None	**-**
T133	Cypress spp.	*Cupressus spp.*	5	SM	3	320	3.8	0.5	0.5	0.5	0.5	-	-	C1	None	None	**-**
T134	Blue spruce	*Picea pungens*	4.5	SM	1	120	1.4	1	1	1	1	2	n/a	C1	Lower branches previously removed	None	**-**
T135	Yew spp. TBC	*Taxus spp.*	3.5	SM	5	250	3.0	5	0.5	0.5	0.5	-	-	C1	Path side section removed leaving unbalanced form	None	**-**
T136	Cypress spp.	*Cupressus spp.*	7	M	1	300	3.6	2	2	2	2	-	-	B1	Lower branches cut back on west side for pedestrian access.	None	**-**
T137	Cypress spp.	*Cupressus spp.*	8	M	1	350	4.2	2	2	2	2	-	-	B1	Lower branches cut back on east side for pedestrian access.	None	**-**

T138	Cypress spp.	*Cupressus spp.*	7	M	1	250	3.0	1	1	1	1	-	-	B1	None	None	-
T139	Cherry spp.	*Prunus spp.*	5	SM	1	100	1.2	1	1	1	1	1	S	C1	None	None	-
T140	Cherry spp.	*Prunus spp.*	10	M	2	420	5.0	6	6	4	5	2	W	A1	Included union between codominant stems at 2.5m.	None	-
T141	Cherry spp.	*Prunus spp.*	8	SM	1	150	1.8	1	1	3	2	0.75	E	B1	None	None	-
T142	Cherry spp.	*Prunus spp.*	10	SM	1	220	2.6	2	2	1	5	2.5	W	B1	None	None	-
T143	Cherry spp.	*Prunus spp.*	4	SM	1	180	2.2	0	0	0	5	2	N	B1	None	None	-
T144	Cherry spp.	*Prunus spp.*	6	SM	1	380	4.6	2	2	2	3	0.5	S	B1	None	None	-
T145	Cherry spp.	*Prunus spp.*	6	SM	1	280	3.4	1	4	5	0	0.5	NE	B1	None	None	-
T146	Ash	*Fraxinus excelsior*	9	SM	1	220	2.6	2	4	1	2	2.5	E	B1	None	None	-
T147	Scots pine	*Pinus sylvestris*	11	SM	1	280	3.4	2	3	3	4	3.5	SW	B1	None	None	-
T148	Scots pine	*Pinus sylvestris*	9	SM	1	310	3.7	1	3	4	1	2	S	B1	None	None	-
T149	Scots pine	*Pinus sylvestris*	8	SM	1	260	3.1	2	1	3	2	2.5	NE	B1	None	None	-
T150	Horse chestnut	*Aesculus hippocastanum*	16	M	1	620	7.4	7	5	6	8	4	N	A1	Patch of bark wounding on stem at 4m height north side; crown appears to be in good vitality with no significant defects recorded.	None	-
T151	Cherry spp.	*Prunus spp.*	8	M	1	330	4.0	3	2	2	6	2.5	S	C1	Dead wood in crown and signs of previous fractures; stem covered with ivy, restricting inspection.	Carefully sever ivy at base of tree.	**2**
T152	Cedar of Lebanon	*Cedrus libani*	9	SM	1	270	3.2	3	4	3	3	2	n/a	B1	None	None	-
T153	Ash	*Fraxinus excelsior*	4.5	SM	1	150	1.8	1.5	2	2	2	2	S	C1	None	None	-
T154	Holly	*Ilex aquifolium*	9	M	1	330	4.0	3	3	3	2	2	n/a	B1	Dense mature holly with shooting from previously cut points.	None	-
T155	Apple	*Malus spp.*	8	M	1	600	7.2	6	5	4	5	2.5	E	A1	Cavity to rear of tree at 1.5m height revealing hollow rotten core extending downwards by at least 0.5m. Some wounds evident in crown but otherwise vitality appears normal.	Suggest specialist formative pruning to reduce weight of limbs and to benefit vitality (will require expert guidance on care of veteran apple trees)	**2**
T156	Holly	*Ilex aquifolium*	7	M	1	300	3.6	2.5	3	2	3	2	n/a	B1	Ivy on trunk.	None	-
T157	Holly	*Ilex aquifolium*	6	M	1	300	3.6	2	2	1.5	2	2	n/a	B1	Ivy on trunk.	None	-
T158	Lime	*Tilia spp.*	5	SM	1	150	1.8	0.5	0.5	2	2	-	-	C1	Growth of tree suppressed by neighbouring trees.	None	-
T159	Lime	*Tilia spp.*	12	SM	1	280	3.4	4	3.5	1.5	3	3	S	B1	Ivy on trunk	Carefully sever ivy at base	**2**
T160	Ash	*Fraxinus excelsior*	14	SM	2	300	3.6	4	2	3	2	6	S	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
T161	Ash	*Fraxinus excelsior*	14	SM	1	390	4.7	1.5	3	4	3	2.5	S	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
G162	Hawthorn, cherry, hazel, field maple	*n/a*	<6	<M	-	-	-	-	-	-	-	-	-	C1	Scrubby border with heavily ivy clad mature stems.	Carefully sever ivy at base of mature stems; consider coppicing younger stems and hazel to manage scrub growth.	**2**
T163	Horse chestnut	*Aesculus hippocastanum*	17	M	1	580	7.0	4	4	4	5	4	580	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
T164	Crab apple TBC	*Malus sylvestris*	9	M	2	460	5.5	6	2	3	3	4.5	N	B1	Heavily ivy clad, restricting inspection, some evidence of previous crown damage	Carefully sever ivy at base	**2**
T165	Crab apple	*Malus sylvestris*	9	M	1	300	3.6	4	2	4	3	-	-	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
T166	Hawthorn	*Crataegus monogyna*	5	M	1	320	3.8	4	2	4	3	3.5	N	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
T167	Crab apple	*Malus sylvestris*	7	M	1	-	-	3	5	5	6	-	-	B1	Heavily ivy clad, restricting inspection	Carefully sever ivy at base	**2**
T168	Field maple	*Acer campestre*	5	SM	1	-	-	-	-	-	-	-	-	U	Heavily ivy clad and tree appears to be in poor condition.	Fell tree	**2**

T169	Sycamore	*Acer pseudoplatanus*	9	SM	1	450	5.4	1	6	6	2	2.5	E	C1	Heavily ivy clad with long limbs over neighbouring buildings; some minor crown damage evident.	Carefully sever ivy at base	**2**
T170	Field maple	*Acer campestre*	17	M	1	610	7.3	5	5	7	4	5	S	A1	3 small patches of black exudate on trunk on east side; cavities (not rotten) present on trunk that could potentially support a bat roost; minor dead wood in crown; two stems with partially grafted union at 2-3m.	Re-inspect tree in 18 months to assess any further decline in condition.	**4**
T171	Cherry	*Prunus spp.*	3.5	SM	1	120	1.4	1	1	1	1	-	-	C1	None	None	-
T172	Oak	*Quercus robur*	22	M	1	1300	15.6	8	11	11	11	2.5	S	A1	Ivy restricting inspection; major dead wood and fractured stubs throughout crown; no other significant defects recorded.	Carefully sever ivy at base; remove all dead wood over 50mm diameter from crown and inspect for further defects while climbing.	**2**
G173	Field maple, blackthorn etc	*n/a*	-	SM	-	-	-	-	-	-	-	-	-	-	Shrub edge extending along most of boundary underneath mature specimens; most trees ivy covered.	None	-
T174	Oak	*Quercus robur*	21	M	1	800	9.6	7	7	7	10	5	S	A1	Fractured stubs in crown of tree from previous failed limbs; major dead wood in crown.	Remove all dead wood over 50mm diameter from crown and inspect for further defects while climbing	**2**
T175	Beech	*Fagus sylvatica*	11	SM	1	480	5.8	3	4	3	9	2	W	B1	Form of tree suppressed and pushed west by neighbouring oak; small cavity at stem union st 2m height.	None	-
T176	Norway maple	*Acer platanoides*	11	SM	1	380	4.6	3	1	3	7	2.5	W	B1	Small patch of bark wounding on trunk; crown dominant on field side.	None	-
T177	Beech	*Fagus sylvatica*	14	SM	1	420	5.0	4	5	4	5	4	N	B1	Small cavity on south side at 2.5m.	None	-
T178	Beech	*Fagus sylvatica*	14	SM	1	400	4.8	4	6	4	5	4	W	B1	None	None	-
T179	Oak	*Quercus robur*	22	M	1	1100	13.2	7	9	9	9	3	S	A1	Ivy restricting inspection; crown appears to be quite sparse possibly as a result of crown dieback; major and minor dead wood throughout; narrow wound on south side of trunk from base to at least 2m height, obscured by ivy.	Carefully sever ivy at base and strip back to a minimum of 3m height to enable inspection of extent of wound; re-inspect tree in 6 months to assess crown vitality.	**1**
T180	Beech	*Fagus sylvatica*	22	M	1	450	5.4	4	4	3	6	3	N	A1	None	None	
T181	Lime	*Tilia spp.*	22	M	1	600	7.2	3	4	5	5	3.5	S	A1	Minor dead wood in lower crown; included union between two co-dominant stems at 3m height	None	
T182	Horse chestnut	*Aesculus hippocastanum*	13	SM	1	420	5.0	4	3	4	4	2	S	B1	Some minor bark cracking and wounding on trunk, potential early stages of bleeding canker.	Re-inspect tree in 18 months to assess any further decline in condition	**4**
T183	Cherry	*Prunus spp.*	11	M	1	420	5.0	4	4	5	4	2.5	S	B1	Dense crown with lots of crossing branches and minor dead wood present; minor bark wounding on trunk	Clean crown and thin by up to 20%	**3**
T184	Beech	*Fagus sylvatica*	23	M	1	500	6.0	6	7	3	4	3	E	A1	Two suspended fractured limbs in crown at 6m and 12m.	Remove suspended limbs	**1**
T185	Lime	*Tilia spp.*	22	M	1	480	5.8	3	5	5	5	2	S	A1	None	None	-
T186	Ash	*Fraxinus excelsior*	23	M	1	850	10.2	7	8	10	11	4	SW	A1	None	None	-
T187	Red oak	*Quercus rubra*	15	SM	1	390	4.7	3	5	6	6	2.5	S	B1	Bark wounding/cracking on boundary side up to 1m height.	None	-

T188	Red oak	*Quercus rubra*	15	SM	1	230	2.8	1	3	2	2	3	NW	B1	Bark wounding/cracking on field side up to 1.5m height.	None	-
T189	Red oak	*Quercus rubra*	17	SM	1	380	4.6	2	5	4	5	2	NW	B1	None	None	-
T190	Red oak	*Quercus rubra*	14	SM	1	200	2.4	3	3	3	2	3	W	B1	None	None	-
T191	Red oak	*Quercus rubra*	15	SM	1	500	6.0	4	4	2	5	2.5	W	B1	Two lengths of dead wood on south side of tree at 2.5m and 3m.	Remove all dead wood over 50mm diameter.	**4**
T192	Cherry spp.	*Prunus spp.*	2.5	M	1	180	2.2	1.5	1.5	1.5	1.5	1.5	N	C1	Fungal brackets in crown; dead wood present.	Re-inspect tree in 18 months to assess any further decline in condition	**4**
T193	Hawthorn	*Crataegus monogyna*	4.5	M	2	175	2.1	3	2	2	2	2	N	B1	None	None	-
T194	Giant redwood	*Sequoiadendron giganteum*	9	SM	1	440	5.3	2	2	2	2	-	-	A1	None	None	-
T195	Himalayan birch	*Betula utilis var. jacquemontii*	6	SM	1	160	1.9	3	3	3	3	0.75	n/a	A1	None	None	-
T196	Persian ironwood	*Parrotia persica*	4	SM	1	100	1.2	1.5	1.5	1.5	1.5	1.5	n/a	B1	None	None	-
G197	Cherry spp, sorbus spp, sycamore, laurel (aucuba), field	*n/a*	<8	<SM	-	-	-	-	-	-	-	-	-	C1	Ornamental shrub border with some small trees, possibly self set.	None	-
T198	Cotoneaster spp.	*Cotoneaster spp.*	7	M	7	320	3.8	4	4	4	4	-	-	B1	None	None	-
T199	Magnolia	*Magnolia spp.*	5.5	M	1	170	2.0	3.5	0	3.5	3.5	0.5	S	B1	None	None	-
T200	Unknown TBC	*n/a*	7	SM	6	245	2.9	2	2	2	2	-	-	B1	None	None	-
T201	Unknown TBC	*n/a*	7	SM	6	245	2.9	2	2	2	2	-	-	B1	None	None	-
T202	Unknown TBC	*n/a*	3.5	SM	2	260	3.1	1	2	3	2	2	S	B1	Bark cracking throughout with minor dead wood; included unions between stems at 2m height.	None	-
T203	Laburnum	*Laburnum spp.*	4	SM	2	180	2.2	2	1	2	2	1	N	B1	Close to building and car park; rubbing damage from fence.	None	-
T204	Yew	*Taxus baccata*	4.5	SM	1	330	4.0	4	3	4	3	2	N	B1	Tree constrained by location - building, wall and car park.	None	-
T205	Oak	*Quercus robur*	11	SM	1	580	7.0	5	6	4	4	2.5	N	A1	3 no. co-dominant stems from sound union at 2m; minor dead wood in crown; low branches over building	Carefully prune back branches to give clearance to building	**3**
T206	Beech	*Fagus sylvatica*	12	SM	1	440	5.3	5	3	3	5	2.5	S	A1	None	None	-
T207	Cypress spp.	*Cupressus spp.*	21	M	1	600	7.2	3	4	3	3	2	N	B1	Crown damage with recently fractured branch at base of tree leaving wound at approx. 6m on north side; at that point the main leader appears to have a bulge suggesting possible internal decay; at least two other snapped hanging branches in crown.	Remove any snapped, hanging branches; inspect wound and bulge at 6m.	**1**
T208	Cherry spp.	*Prunus spp.*	8	M	2	290	3.5	3	3	3	3	2.5	S	B1	Included union between two stems with some signs of decay; tree growing over awning and creating a mess from leaf drop; roots have caused significant damage to concrete surface.	Consider felling tree to improve garden conditions.	**4**
T209	Silver birch	*Betula pendula*	14	SM	1	280	3.4	3	3	3	3	3	S	A1	None	None	-
T210	Silver birch	*Betula pendula*	10	SM	1	180	2.2	2	2	2	2	-	-	B1	None	None	-
T211	Silver birch	*Betula pendula*	6	SM	1	260	3.1	2	3	2	2	4	S	C1	Poor crown form	None	-

T212	Cherry spp.	*Prunus spp.*	6	M	1	320	3.8	3	3	3	3	2.5	W	B1	*Phellinus pomaceus* fungus in crown but doesn't currently appear to be causing too many problems; good crown form and vitality	Re-inspect tree in 18 months to assess any further decline in condition as a result of the fungus	**4**
T213	Field maple	*Acer campestre*	8	M	1	560	6.7	2	4	4	2	2.5	W	B1	None	None	**-**
T214	Field maple	*Acer campestre*	8	M	2	290	3.5	2	2	3	3	2	S	B1	None	None	**-**
T215	Sycamore	*Acer pseudoplatanus*	12	M	2	512	6.1	5	5	5	5	2.5	n/a	B1	Tree previously pollarded with good regrowth from cut points; ivy restricting inspection.	Carefully sever ivy at base; consider re-pollarding tree within the next few years	**2**
T216	Cherry plum	*Prunus cerasifera*	8	M	2	590	7.1	5	4	3	5	2	N	C1	Rotten cavities throughout crown with *Phellinus pomaceus* fungal fruiting bodies present; evidence of previous limb fractures; crown previously reduced	Reduce crown to a finished height of 5-6m and spread of 3-4m to reduce risk of further stem fracture	**2**
T217	Cherry plum	*Prunus cerasifera*	7	M	1	510	6.1	3	3	3	3	2	S	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T218	Hawthorn	*Crategus monogyna*	7	M	1	780	9.4	4	4	4	3	-	-	B1	Crown dense with ivy, restricting inspection	Carefully sever ivy at base	**2**
T219	Apple	*Malus spp.*	3.5	M	1	180	2.2	2	2	2	2	2	W	B1	None	None	**-**
T220	Apple	*Malus spp.*	3.5	M	1	230	2.8	2	3	2	1	1.5	E	B1	None	None	**-**
T221	Corkscrew hazel	*Corylus avellana contorta*	3	M	6	240	2.9	1	1	1	1	-	-	A1	None	None	**-**
G222	Cypress spp. X 3	*Cupressus spp.*	<7	SM	3	-	-	2	2	2	2	-	-	B1	None	None	**-**
T223	Ash	*Fraxinus excelsior*	11	M	1	650	7.8	4	4	4	4	4	W	B1	Ivy on stem	Carefully sever ivy at base	**2**
G224	Cypress x 3	*Cupressus spp.*	<9	SM	3	-	-	2	2	2	2	-	-	B1	Crowns heavily ivy clad	Carefully sever ivy at base	**2**
T225	Ash	*Fraxinus excelsior*	16	M	1	920	11.0	5	5	6	6	5	W	A1	Branch fracture at 5m on west side; ivy restricting inspection of trunk.	Carefully sever ivy at base	**2**
T226	Field maple	*Acer campestre*	8	M	1	720	8.6	4	6	7	6	4	N	B1	Ivy restricting inspection; dead wood in crown and some gaps in canopy from previous limb failures.	Carefully sever ivy at base	**2**
T227	Cherry spp.	*Prunus spp.*	5	SM	1	190	2.3	2	2	3	3	-	-	B1	None	None	**-**
T228	Cherry plum	*Prunus cerasifera*	8	M	1	320	3.8	3	5	2	1	3	E	B1	Dense shooting in crown and epicormic growth from base.	Cut back epicormic basal growth.	**4**
T229	Field maple	*Acer campestre*	11	M	1	460	5.5	4	4	2	2	2	W	B1	Some dead wood in crown with signs of moderate vitality.	None	**-**
T230	Hawthorn	*Crataegus monogyna*	6	M	1	630	7.6	1	1	2	6	-	-	U	Heavily ivy covered with little sign of vitality; tree leaning over fence towards neighbouring property.	Fell tree	**1**
T231	Copper beech	*Fagus sylvatica*	17	M	1	560	6.7	5	5	5	5	4	S	A1	Minor dead wood in crown; no other significant defects recorded.	None	**-**
T232	Hawthorn	*Crategus monogyna*	5	M	2	-	-	-	-	-	-	-	-	U	Heavily ivy clad tree appears to have collapsed over fence.	Fell tree	**2**
T233	Ash	*Fraxinus excelsior*	17	M	1	640	7.7	5	5	5	5	4	SW	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
G234	Mixed broadleaf shrubs (hawthorn etc)	*n/a*	<5	<M	10	-	-	-	-	-	-	-	-	C1	Group of predominantly hawthorn, heavily ivy clad restricting inspection; no other significant defects recorded.	Carefully sever ivy at base of trees	**4**
G235	Cypress spp. X 12	*Cupressus spp.*	<9	SM	4	<280	-	2.5	2.5	2.5	2.5	-	-	B1	Included union between stems of tree on west end of group.	None	**-**
T236	Cypress	*Cupressus spp.*	Na	SM	1	-	-	-	-	-	-	-	-	U	Collapsed ivy clad cypress leaning across another tree in direction of path (although no risk to path users).	Cut up and clear fallen tree	**2**
T237	Holly	*Ilex aquifolium*	3	M	1	190	2.3	1.5	1.5	1.5	1.5	0.5	n/a	B1	None	None	**-**
T238	Yew	*Taxus baccata*	4	SM	MS	350	4.2	1.5	1.5	1.5	1.5	-	-	B1	None	None	**-**
T239	Yew	*Taxus baccata*	4	SM	MS	350	4.2	1.5	1.5	1.5	1.5	-	-	B1	None	None	**-**

T240	Paper bark maple	*Acer griseum*	4	SM	1	160	1.9	2	2	2	2	1	N	B1	None	None	-
T241	Field maple	*Acer campestre*	6	SM	1	210	2.5	3	3	3	3	2	W	B1	None	None	-
G242	Yew x 3	*Taxus baccata*	5	SM	3	<350	-	1.5	1.5	1.5	1.5	-	-	B1	None	None	-
T243	Silver birch	*Betula pendula*	15	M	1	490	5.9	5	4	5	5	2.5	S	C1	Crown in poor vitality with inspection obscured by dead ivy; evidence of previous limb failure; minor dead wood in crown and signs of dieback.	Re-inspect tree in 18 months to assess any further decline in condtion.	**4**
T244	Cherry spp. TBC	*Prunus spp.*	6	M	3	350	4.2	3	3	3	4	2	E	C1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T245	Holm oak TBC	*Quercus ilex*	7	SM	3	495	5.9	3	2	5	6	2.5	NW	B1	None	None	-
T246	Hawthorn	*Crataegus monogyna*	5	M	1	340	4.1	2	2	2	3	2.5	W	C1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T247	Field maple	*Acer campestre*	6	SM	3	196	2.4	5	4	2	4	2	E	B1	None	None	-
T248	Ash	*Fraxinus excelsior*	8	SM	1	220	2.6	5	4	4	3	2.5	N	B1	Tree located next to street lamp but not currently obstructing	None	-
T249	Sycamore	*Acer pseudoplatanus*	14	M	1	880	10.6	7	7	7	7	2	E	A1	Minor dead wood in crown; no other significant defects recorded.	None	-
T250	Ash	*Fraxinus excelsior*	19	M	1	540	6.5	6	5	6	6	4.5	W	B1	Major dead wood in crown and potentially signs of minor dieback.	Remove all dead wood over 50mm diameter; Re-inspect tree in 18 months to assess any further decline in condition.	**1**
T251	Plum TBC	*Prunus domestica*	4.5	SM	3	158	1.9	2	2	3	2	-	-	B1	None	None	-
T252	Plum TBC	*Prunus domestica*	3	SM	1	190	2.3	1	1	1	1	1.5	N	B1	None	None	-
T253	Plum TBC	*Prunus domestica*	3	SM	1	160	1.9	1	1	1	1	1.75	S	B1	None	None	-
T254	Plum TBC	*Prunus domestica*	4	M	2	264	3.2	2	1	1	1	2	N	B1	None	None	-
T255	Unknown broadleaf	*n/a*	4.5	SM	1	170	2.0	2	2	2	2	2	NE	B1	None	None	-
T256	Cherry TBC	*Prunus spp.*	4.5	SM	1	350	4.2	3	3	3	3	1.5	E	B1	None	None	-
T257	Ash	*Fraxinus excelsior*	15	M	1	520	6.2	4	4	5	5	2.5	NW	B1	There appears to be an included union between two co-dominant stems at 1.75m height; minor dead wood in crown; ivy restricting inspection.	Carefully sever ivy at base.	**2**
G258	Mixed broadleaves	*n/a*	<4	SM	5	-	-	-	-	-	-	-	-	U	A number of collapsed heavily ivy clad stems over property boundary.	Cut up and clear any fallen or fractured trees.	**1**
T259	Holly	*Ilex aquifolium*	5	M	6	320	3.8	3	3	3	3	-	-	B1	None	None	-
T260	Alder	*Alnus glutinosa*	11	SM	1	110	1.3	1.5	1.5	1.5	1.5	5	S	C1	None	None	-
T261	Hawthorn	*Crataegus monogyna*	6	M	2	264	3.2	2	2	2	2	-	-	B1	None	None	-
T262	Cypress spp.	*Cupressus spp.*	12	M	1	330	4.0	1	4	2	2	2	N	C1	Included union between codominant stems at 4m height.	None	-
T263	Beech	*Fagus sylvatica*	20	SM	1	460	5.5	2	2	6	8	3	W	C1	Large wound at 3-4m height on east side of tree revealing rotten core; good crown vitality but weighted to west away from neighbouring trees.	Suggest felling tree due to close proximity to other beech and location next to site entrance and footpath	**1**
T264	Beech	*Fagus sylvatica*	20	SM	1	480	5.8	4	6	7	6	2.5	E	B1	None	None	-
T265	Beech	*Fagus sylvatica*	20	SM	1	530	6.4	4	6	2	6	2	E	B1	None	None	-
T266	Cherry	*Prunus spp.*	8	M	3	280	3.4	3	3	3	3	2	SW	B1	None	None	-
T267	Silver birch	*Betula pendula*	18	M	1	360	4.3	3	3	3	3	2.5	W	A1	None	None	-
T268	Rowan	*Sorbus aucupaira*	4	SM	1	80	1.0	2.5	2.5	2.5	2.5	1	S	B1	None	None	-
T269	Hornbeam	*Carpinus betulus*	19	M	1	530	6.4	5	6	5	5	0.5	S	A1	Minor dead wood in crown	None	-
T270	Beech	*Fagus sylvatica*	20	SM	1	430	5.2	5	6	7	5	3	E	A1	None	None	-
T271	Hornbeam	*Carpinus betulus*	17	SM	1	330	4.0	0	6	6	3	2.5	W	B1	None	None	-
T272	Hornbeam	*Carpinus betulus*	16	SM	1	280	3.4	3	2	2	1	2.5	S	B1	None	None	-

T273	Unknown - dead	*n/a*	3	SM	-	-	-	-	-	-	-	-	-	U	There appears to be dead ivy covered tree collapsed against hornbeams but difficult to confirm due to density of ivy.	Cut up and clear fallen tree.	**2**
T274	Lime	*Tilia spp.*	17	SM	2	470	5.6	4	4	2	3	4	N	A1	None	None	**-**
T275	Sycamore	*Acer pseudoplatanus*	16	SM	1	380	4.6	3	3	3	3	5	E	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T276	Lime	*Tilia spp.*	14	SM	1	240	2.9	3	3	3	3	4	E	B1	None	None	**-**
T277	Ash	*Fraxinus excelsior*	19	SM	1	330	4.0	4	4	4	4	6	n/a	B1	Longitudinal wound on east side of tree from 0.75m to 2m height	None	**-**
T278	Sycamore	*Acer pseudoplatanus*	19	M	1	420	5.0	3	5	5	4	3	SW	B1	Ivy restricting inspection; squirrel damage to limbs	Carefully sever ivy at base	**2**
T279	Sycamore	*Acer pseudoplatanus*	17	M	1	480	5.8	6	6	6	6	4	S	B1	Ivy restricting inspection; minor dead wood in crown;	Carefully sever ivy at base	**2**
T280	Field maple	*Acer campestre*	16	M	1	340	4.1	1	4	5	4	6	W	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T281	Lime	*Tilia spp.*	18	M	1	360	4.3	4	4	4	4	5	S	A1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T282	Field maple	*Acer campestre*	15	M	2	295	3.5	1	3	3	1	3	S	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T283	Field maple	*Acer campestre*	15	M	1	230	2.8	1	1	3	4	5	W	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T284	Field maple	*Acer campestre*	15	M	1	190	2.3	1	3	3	1	5	S	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T285	Sycamore	*Acer pseudoplatanus*	16	SM	1	230	2.8	1	1	3	5	4	W	U	Poor form and crown vitality; ivy restricting inspection.	Carefully sever ivy at base; re-inspect tree in 18 months to assess any further decline in condition	**2**
T286	Lime	*Tilia spp.*	20	M	1	420	5.0	5	5	5	5	3	SE	A1	None	None	**-**
T287	Lime	*Tilia spp.*	20	M	1	420	5.0	5	5	5	5	3	SE	A1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T288	Hawthorn	*Crataegus monogyna*	6	M	1	280	3.4	3	3	3	3	-	-	U	Tree heavily ivy clad; little sign of living branches	Fell tree	**2**
T289	Sycamore	*Acer pseudoplatanus*	20	M	1	370	4.4	5	5	5	5	2.5	NW	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T290	Sycamore	*Acer pseudoplatanus*	18	M	1	410	4.9	4	4	4	4	5	E	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
G291	Mixed broadleaves - sycamore, field maple	*n/a*	<18	<M	-	-	-	-	-	-	-	-	-	C1	Ivy restricting inspection throughout whole group; some fallen stems within group; branches overhanging but not obstructing pavement and road.	Check management responsibility of verge; carefully sever ivy at base and clear any fallen stems; re-inspect group in 18 months to assess any further decline in condition.	**2**
T292	Cherry	*Prunus spp.*	6	SM	1	130	1.6	1	2	3	3	2	S	C1	None	None	**-**
T293	Cherry	*Prunus spp.*	6	M	1	290	3.5	4	4	4	4	2	S	B1	None	None	**-**
T294	Cherry	*Prunus spp.*	7	M	1	240	2.9	3	3	3	3	2	W	B1	None	None	**-**
T295	Cherry	*Prunus spp.*	7	M	1	320	3.8	4	4	5	4	2	n/a	B1	Included stem union at 2m	None	**-**
T296	Alder	*Alnus glutinosa*	9	SM	1	210	2.5	2	4	4	2	2.5	N	B1	None	None	**-**
T297	Alder	*Alnus glutinosa*	8	SM	1	200	2.4	3	4	3	3	2.5	N	B1	None	None	**-**
T298	Unknown - broadleaf	*n/a*	5	SM	1	120	1.4	3	3	3	3	2	n/a	C1	None	None	**-**
T299	Unknown - broadleaf	*n/a*	5	SM	2	110	1.3	1.5	1.5	1.5	1.5	1	S	C1	None	None	**-**
T300	Oak	*Quercus robur*	5	Y	1	250	3.0	-	-	-	-	2.5	S	C1	Large stem fracture wound at 3-4m leaving crown in poor form.	Either remove remaining stem to just below fracture to see whether tree will respond positively OR fell tree and replace.	**2**

T301	Horse chestnut	*Aesculus hippocastanum*	15	M	1	1080	13.0	2	4	8	2	5	SW	B1	Hole at approx. 4.5m on south side; two further holes at same height on north side; crown previously reduced but leaving limbs on building side intact; decay visible at former cut points; crown now dominant towards building; potential for holes to support bat roosts.	Climbing inspection (preferably by or with a Level 2 bat licensed ecologist) to assess extent of holes and any other significant defects present.	**1**
T302	Sycamore	*Acer pseudoplatanus*	13	SM	1	270	3.2	1	1	4	4	3.5	SE	B1	None	None	-
T303	Ash	*Fraxinus excelsior*	14	SM	1	290	3.5	2	2	5	5	4	SE	B1	Included union between two co-dominant stems; rubbing points on stem in two places; crown form is good but concern over direction of stems and proximity to play area	Fell tree	**1**
T304	Sycamore	*Acer pseudoplatanus*	15	M	2	650	7.8	2	8	7	3	2	N	B1	Included union between two stems at 2m height.	None	-
T305	Oak	*Quercus robur*	19	M	1	870	10.4	9	8	8	9	4	N	B1	Damage to bark from poor severing of ivy; crown previously opened up (possibly as a result of stem fracture) leaving a sparse form with far reaching limbs; appears to be in poor vitality.	Re-inspect tree in 6 months to view vitality and form in leaf.	**2**
T306	Cherry	*Prunus spp.*	7	SM	1	190	2.3	2	4	3	1	2.5	N	B1	None	None	-
T307	Ash	*Fraxinus excelsior*	9	SM	1	230	2.8	2	2	3	3	2.5	E	C1	Tree growing underneath large oak limb	None	-
T308	Lime	*Tilia spp.*	9	SM	1	270	3.2	3	4	5	5	2.5	N	C1	Tree growing underneath large oak limb; slight kinks in trunk.	None	-
T309	Ash	*Fraxinus excelsior*	19	M	1	360	4.3	5	6	7	6	8	S	B1	None	None	-
T310	Cherry spp.	*Prunus spp.*	4.5m	SM	1	110	1.3	2	2	2	2	2	N	C1	None	None	-
T311	Tulip tree	*Liriodendron tulipifera*	6.5	SM	1	140	1.7	2.5	2.5	2.5	2.5	2.5	S	B1	None	None	-
G312	Ash x 2	*Fraxinus excelsior*	7	SM	3	170	2.0	3	3	3	3	1.5	SE	B1	Lower branches growing into green house	Crown lift tree to 2.5-3m height	**3**
T313	Field maple	*Acer campestre*	7	SM	2	240	2.9	4	3	0	3	1.75	NE	B1	None	None	-
T314	Cherry plum	*Prunus cerasifera*	7	M	1	370	4.4	5	4	4	4	1.5	NE	B1	None	None	-
T315	Field maple	*Acer campestre*	7.5	SM	1	190	2.3	0	3	3	3	1	S	B1	None	None	-
T316	Field maple	*Acer campestre*	7	SM	1	170	2.0	3	3	3	3	1.5	SW	B1	None	None	-
T317	Beech	*Fagus sylvatica*	7	Y	2	145	1.7	1	3	3	3	1.75	SW	C1	Included union between two stems and a couple of rubbing points caused by close proximity.	None	-
T318	Cherry	*Prunus spp.*	4	SM	2	105	1.3	0	3	2	3	-	-	U	Poor union between two stems at base; one stem growing across gate and path; bark damage on both stems.	Fell tree	**2**
T319	Horse chestnut	*Aesculus hippocastanum*	7	SM	2	234	2.8	3	3	3	3	2.5	E	B1	Included unions between main stems with water pockets.	None	-
T320	Ash	*Fraxinus excelsior*	17	M	1	500	6.0	6	6	5	6	2	E	A1	Dense crown with minor dead wood throughout and lots of surrounding debris blown out from recent winds; a few minor hanging branches still in crown.	Clean crown of as much dead wood as possible; re-inspect tree in 6 months to assess need for a crown thinning operation.	**2**
T321	Apple	*Malus spp.*	5	M	1	410	4.9	4	4	4	4	1.5	E	A1	Long limbs growing out across fence and over neighbouring property garden and shed; no significant defects recorded	None	-
T322	Apple	*Malus spp.*	4	M	2	288	3.5	3	3	3	2	2	NE	A1	Tree recently pruned	None	-

T323	Apple	*Malus spp.*	4	M	1	240	2.9	2	1	2	2	1.5	N	B1	Tree recently pruned; growing close to fence and slightly suppressed by neighbouring yew.	Trim back yew branches to boundary fence.	**4**
T324	Apple	*Malus spp.*	4	M	2	290	3.5	2.5	3	4	3	1.5	N	A1	Small rot pockets associated with previous pruning cuts; tree recently pruned	None	**-**
T325	Apple	*Malus spp.*	4	M	4	356	4.3	3	2	4	3	1.5	S	A1	Growing close to boundary fence but pruned back so as not to cross it; tree recently pruned; large pocket of rot on one stem at 1.5m height.	None	**-**
T326	Apple	*Malus spp.*	4	M	4	320	3.8	3	3	3	3	2	W	A1	Tree recently pruned.	None	**-**
T327	Apple	*Malus spp.*	4	M	2	248	3.0	2	4	4	2	2	S	A1	Tree recently pruned.	None	**-**
T328	Apple	*Malus spp.*	6	M	4	315	3.8	3	3	4	4	2	NW	A1	Tree recently pruned.	None	**-**
T329	Apple	*Malus spp.*	4	M	2	205	2.5	2	3	3	2	1.5	SE	A1	Tree recently pruned.	None	**-**
T330	Weeping willow	*Salix babylonica*	23	M	1	480	5.8	6	6	6	6	2.5	NW	A1	Minor and occasional major dead wood throughout crown; there appears to be a split limb at approx. 18m height in centre-west of tree; canopy very low and no doubt causes shading and obstruction during summer (although potentially desirable for outdoor classroom).	Clean crown of dead wood over 25mm diameter and remove split limb at 18m; discuss with staff potential for crown lifting.	**1**
T331	Lombardy poplar	*Populus nigra 'Italica'*	26	M	1	360	4.3	3	3	3	3	-	-	B1	None	None	**-**
T332	Cypress spp.	*Cupressus spp.*	18	M	1	310	3.7	2.5	2.5	2.5	2.5	-	-	B1	Ivy restricting inspection	Carefully sever ivy at base	**3**
T333	Sycamore	*Acer pseudoplatanus*	9	SM	1	170	2.0	3	3	1	3	3	S	C1	Tree surrounded by mature shrubs; longitudinal wound on east side of trunk with internal rot.	None	**-**
T334	Cherry plum TBC	*Prunus cerasifera*	6.5	M	1	560	6.7	6	4	1	3	1.5	N	B1	Tree has a pronounced leaning habit towards north with great weight on over extended lateral limbs; ivy partially obscuring inspection; surprisingly little visible evidence of rot or other significant defects, however concern over future integrity of limbs.	Carefully sever ivy at base; consider propping over extended limb if retention is desirable or sensitive crown reduction to reduce weight.	**2**
T335	Sycamore	*Acer pseudoplatanus*	13	M	1	360	4.3	2	5	5	3	4.5	N	C1	Ivy restricting inspection; dead wood in crown and dieback	Fell tree	**2**
T336	Lombardy poplar	*Populus nigra 'Italica'*	23	SM	1	230	2.8	1	1	1	1	-	-	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T337	Ash	*Fraxinus excelsior*	20	M	1	230	2.8	0	4	5	0	3	E	B1	Ivy restricting inspection	Carefully sever ivy at base	**2**
T338	Sycamore	*Acer pseudoplatanus*	20	M	1	340	4.1	3	3	3	3	4	N	B1	Ivy restricting inspection; note tree adjacent to one semi-mature ivy covered dead stem (sprayed with paint)	Carefully sever ivy at base; fell dead stem.	**2**
T339	Sycamore	*Acer pseudoplatanus*	20	M	1	240	2.9	0	3	5	0	2.5	E	B1	Ivy restricting inspection; squirrel damage to limbs; major dead limb at 2.5m on SE side (heading towards house)	Carefully sever ivy at base; remove dead limb.	**2**
T340	Sycamore	*Acer pseudoplatanus*	21	M	1	620	7.4	6	6	6	6	3	N	A1	Ivy restricting inspection; no other significant defects recorded, although very large crown in close proximity to neighbouring property	Carefully sever ivy at base; consider sensitive crown reduction by up to 30%	**2**
T341	Swamp cypress	*Taxodium distichum*	20	M	1	750	9.0	4	4	4	4	2.5	SW	A1	Tree appears to be in good condition with no significant defects recorded; a few lengths of minor dead wood in crown	None	**-**

T342	Ash	*Fraxinus excelsior*	21	M	2	532	6.4	7	7	6	6	6.5	N	A1	Two stems from included union at base; crowns dense and in normal vitality with little sign of dieback; minor dead wood in crown and some evidence of branch drop on ground around tree; very close to neighbouring property.	Either sensitively reduce crown by up to 30% and remove any dead wood while climbing OR completely remove stem which is growing out across neighbouring land.	**2**
T343	Hawthorn TBC	*Crataegus monogyna*	7	M	1	390	4.7	3	1	0	3	-	-	C1	Ivy restricting thorough inspection	Carefully sever ivy at base	**2**
G344	Cypress x 4	*Cupressus spp.*	<8	SM	4	260	3.1	2	2	2	2	-	-	U	One tree showing significant dieback in lower limbs of tree; others also showing some dieback.	Re-inspect group in 18 months to assess any further decline in condition	**4**
T345	Ash	*Fraxinus excelsior*	20	M	1	460	5.5	7	5	4	5	5	N	A1	Ivy and cypress restricting inspection, no significant defects recorded in the crown	Carefully sever ivy at base	**2**
T346	Ash	*Fraxinus excelsior*	9	M	1	330	4.0	12	2	0	2	3	NE	C1	Tree has poor form with crown growing almost horizontally over neighbouring property; some dead wood in crown; doesn't currently appear to be causing too much of a nuisance, but has potential to in future.	None.	-
T347	Ash	*Fraxinus excelsior*	19	M	1	400	4.8	6	6	4	4	5	S	B1	Minor dead wood in crown; ivy restricting inspection.	Carefully sever ivy at base.	-
T348	Willow	*Salix spp.*	14	SM	1	200	2.4	1	2	1	1	2.5	E	B1	None	None	-
T349	Willow	*Salix spp.*	13	SM	1	224	2.7	2	4	2	2	2	E	B1	None	None	-
T350	Yew	*Taxus baccata*	4	SM	1	190	2.3	0	2	3	2	-	-	B1	None	None	-
G351	Mixed broadleaves and shrubs incl. 2 no. Semi mature ash	*n/a*	<7	<M	-	-	-	-	-	-	-	-	-	B1	None	None	-
T352	Yew	*Taxus baccata*	5	SM	1	450	5.4	3	3	3	3	-	-	B1	None	None	-
T353	Unknown - broadleaf	*n/a*	7	M	1	880	10.6	0	4	4	3	2	W	B1	Old mature tree with extensive areas of rotten wood throughout crown; some limbs have previously been reduced; dead wood in crown; metal bar stuck in tree at 2.5m; ivy restricting inspection of base of tree.	Carefully strip ivy from tree to 3m height; re-inspect tree in 18 months.	**2**
T354	Unknown - broadleaf	*n/a*	8	M	1	220	2.6	4	2	2	2	6	S	C1	One main stem and three neighbouring smaller stems that are growing very close to the fire escape.	Recommend felling tree to remove potential obstruction.	**2**
G355	Mixed broadleaves	*n/a*	<8	M	-	-	-	-	-	-	-	-	-	C1	Mixed scrubby group of over mature shrubs and self set trees with dense snowberry and other scrubby plants; unable to thoroughly inspect due to undergrowth and dense ivy	Consider 'reclaiming' area by clearing out scrub and over mature shrubs, and severing ivy at base of retained trees	**2**
T356	Silver birch	*Betula pendula*	3.5	SM	1	80	1.0	1.5	1.5	1.5	1.5	2	N	C1	None	None	-
T357	Silver birch	*Betula pendula*	5	SM	1	130	1.6	2	2	2	2	1.5	S	C1	None	None	-
T358	Silver birch	*Betula pendula*	7	SM	1	160	1.9	2.5	2.5	2.5	2.5	2	E	B1	None	None	-
T359	Silver birch	*Betula pendula*	6	SM	1	130	1.6	2	2	2	2	2	E	C1	None	None	-
T360	Silver birch	*Betula pendula*	4	SM	1	70	0.8	2	2	2	2	2	SW	C1	None	None	-
T361	Silver birch	*Betula pendula*	6	SM	1	130	1.6	2.5	2.5	2.5	2.5	2.5	SW	C1	None	None	-
T362	Silver birch	*Betula pendula*	3.5	SM	1	70	0.8	1	1	1	1	2	W	C1	None	None	-
G363	Dead stems x 3	*n/a*	9	SM	3	-	-	-	-	-	-	-	-	U	Two standing ivy clad dead stems (likely elm) and at least one fallen across shed.	Fell dead trees and cut up & clear fallen stems (check responsibility for carrying out works).	**1**

T364	Cherry spp.	*Prunus spp.*	3.5	SM	1	250	3.0	2	2	2	2	1.5	E	C1	Bark damage and cracking; very low crown close to play equipment	Formative crown prune	**4**
T365	Hazel	*Corylus avellana*	7	M	15<	-	-	4	3	4	3	-	-	B1	Good form for multi-stemmed hazel	None	**-**
T366	Cherry spp.	*Prunus spp.*	6	M	1	400	4.8	3	3	3	3	1.5	S	B1	None	None	**-**

Tree tag	Confirm species
1038	
1037	
1084	

	TBC
	TBC
	TBC
	TBC
	TBC
	TBC
1005	
	TBC

1006	
	TBC
1008	
1007	
1010	

1200	
1199	
1198	

1197	
1195	
	TBC
	TBC
	TBC
	TBC

				1193														

	TBC
	TBC
	TBC
1192	



	TBC
	TBC
	TBC
	TBC
	TBC
	TBC
	TBC
	TBC
	TBC

	TBC

	TBC
	TBC
	TBC

CATEGORY		SUB-CATE
A	Trees of high quality with an estimated remaining life expectancy of at least 40 years	1
B	Trees of moderate quality with an estimated remaining life expectancy of at least 20 years	2
C	Trees of low quality with an estimated remaining life expectancy of at least 10 years, or young trees with a stem diameter below 150mm	3
U	Those in such a condition that they cannot realistically be retained as living trees in the context of the current land use of longer than 10 years	

GORY
Mainly arboricultural qualities
Mainly landscape qualities
Mainly cultural values, including conservation.

For 2 to 5 Stems

Stem No.	DBH (mm)	DBH 2		
	1	0	0	
	2	0	0	
	3	0	0	
	4	0	0	
	5	0	0	
			0	**0.0**

For 6 to 10 Stems

Mean DBH		0	0	
No of Stems			0	
			0	**0.0**