

PHOTOMONTAGE

UPTON HOUSE
4 Baldock Street
ROYSTON
Hertfordshire
SG8 5AY



Photo taken from the rear (south) courtyard, adjacent the modern office structure, looking back at the rear (south) elevation of Upton House



Photo taken from the rear (southern) boundary, looking west towards the former Morrisons building.



Photo taken from the rear (south) courtyard, adjacent the modern office structure, looking at the east elevation of the office building



Photo taken from the position of the existing fire exit, looking west towards the former Morrisons building



Photo taken from the first floor office window over existing flat roof rear extension



Photo taken from the half landing of principal stair case, over existing flat roof rear extension



Photo taken from within The King James Suite (modern flat roof extension to rear).



Photo taken from inside the Priory Suite, proposed to be retained as 'Work Way'



Photo taken from within the principal hallway. Access to the Priory and Francis Hedges Suites to the left, access to the Palace Suite, kitchen and Montague Suite to the rights, access to the King James Suite and toilets straight on.



Photo taken from the entrance to the Montague Suite



Photo taken from the entrance to the Palace Suite