



Report No: 1920378 L01 (00)

PHOTOGRAPHIC LOG

Client name:
Martin Grant Homes

Site Location:
London Road, Hitchin

Date:
03.12.2018

No. 11

Description:
TP7



No. 12

Description
TP8





Report No: 1920378 L01 (00)

PHOTOGRAPHIC LOG

Client name:
Martin Grant Homes

Site Location:
London Road, Hitchin

Date:
03.12.2018

No. 13

Description:
TP9



No. 14

Description
TP10





Report No: 1920378 L01 (00)

PHOTOGRAPHIC LOG

Client name:
Martin Grant Homes

Site Location:
London Road, Hitchin

Date:
03.12.2018

No. 15


Description:
TP11



No. 16

Description
TP12





APPENDIX B

Walkover Survey Photographs



Project:	Mill Lane, Hitchin			Title	Photo Reference Plan		
Client:	Martin Grant Homes			Geo-Environmental Services Ltd Unit 7 Danworth Farm, Cuckfield Road Hurstpierpoint, West Sussex BN6 9GL +44(0)1273 832972 www.gesl.net		 Geo-Environmental	
Ref No:	GE23305	Revision:					
Drawn:		Date:	01/09/2025				
Figure:		Scale:					





1



2



3



4



5



6



7



8



9



10



11



12



13



14



15



16



17



18



19



20



21



22



23



24