

# LEVEL MONITORING

## for SMS (ACR)

**28 Rowan Crescent, Letchworth Garden City, SG6 4EY**

|                   |                        |
|-------------------|------------------------|
| Client:           | SMS (ACR)              |
| Client Contact:   | Refer to iSubs         |
| Claim Number:     | SHAC2511190104         |
| Client Reference: | IFS-ACR-SUB-25-0125711 |
| Policy Holder:    | Gail Dennehy           |
| Report Date:      | 10 June 2026           |
| Our Ref:          | M26284                 |



## Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

| Date       | 1       | 2       | 3      | 4      | 5      | 6      | 7       | 8       | 9       | 10      |
|------------|---------|---------|--------|--------|--------|--------|---------|---------|---------|---------|
| 03/03/2026 | 10.0000 | 10.0025 | 9.9877 | 9.5170 | 9.7323 | 9.7836 | 10.0584 | 10.8436 | 10.8425 | 10.0434 |
| 08/04/2026 | 10.0000 | 10.0029 | 9.9879 | 9.5164 | 9.7327 | 9.7848 | 10.0591 | 10.8429 | 10.8422 | 10.0433 |
| 03/06/2026 | 10.0000 | 10.0028 | 9.9876 | 9.5170 | 9.7328 | 9.7849 | 10.0592 | 10.8438 | 10.8428 | 10.0435 |



## Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



## Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

## Site Visit Notes

Datum is point 1 to rear right and corner of the property as requested. This has an assumed value of 10.0000.