




1. Conventional Cottage Window (Window 1)




2. Conventional Cottage Window (Window 2)




3. Conventional Cottage Window (Window 3)




4. Conventional Cottage Window (Window 4)



5. Conventional Cottage Window (Window 5)



6. Sealed close Cottage Window (Window 6) 26x23, 99x123



Rotten and broken window in Child bedroom



Water tracking and drips in lounge -> suspected from ingress water from upstairs window



Window 6 showing damage.

