

Rustling End Farmhouse, SG4 8TD

Single-storey glazed infill link on north elevation and single-storey glazed link between Farmhouse and Henhouse on west elevation. Internal and external alterations to Henhouse and Stables to facilitate conversion to additional ancillary accommodation

REF-03/25-Photo Survey

Date: 12/04/2024

Photosurvey conducted 11/03/2024

SECTION 1: HENHOUSE

Henhouse external front



Henhouse external Rear



Henhouse external LHS



Henhouse external RHS



Henhouse internal LH Wall



Henhouse internal Rear Wall



Structural Truss & Central partition



Henhouse internal Front wall



Henhouse internal details



Henhouse internal RH wall



Henhouse internal Rear Wall



Structural Truss & Central partition



Henhouse internal Front wall



SECTION 2: GABLE END – Main Farmhouse

Gable end (existing kitchen inside)



Form link to
henhouse using
existing
extension
window

UTILITY ROOM internal



North elevation of farmhouse



SECTION 3: REDUNDANT STABLES

Partition 1: Open Store



Internal Existing Entrance



Internal Rear wall



Internal Dividing wall



Internal front wall



REDUNDANT STABLES

Partition 2: – Oil Tank Store

Wall to open store



Rear wall



Wall to log store



Front wall



REDUNDANT STABLES

Partition 3: Log Store
Wall to oil tank room



Wall to barn



Rear wall



Front wall

