

A:\5200 Series\5297 - The Highfields School\Tech\ACAD\Current\5297-RPS-XX-XX-DR-AR-9000.dwg




© 2024 RPS Group
Notes
1. This drawing has been prepared in accordance with the scope of RPS's appointment with its client and is subject to the terms and conditions of that appointment. RPS accepts no liability for any use of this document other than by its client and only for the purposes for which it was prepared and provided.
2. If received electronically it is the recipients responsibility to print to correct scale. Only written dimensions should be used.
3. This drawing should be read in conjunction with all other relevant drawings and specifications.
4. Where applicable Ordnance Survey (c) Crown Copyright 2024
All rights reserved. Licence number AC0000808122

Safety, Health & Environment Information
In addition to the hazards / risks normally associated with the types of work detailed on this drawing take note below. It is assumed that all works on this drawing will be carried out by a competent contractor, working, where appropriate, to an appropriate method statement.

Construction risks	Maintenance/Cleaning risks	Demolition/Adaption risks

Key

 Individual Tree with numbered reference.
(BS5837:2012 tree quality category as shown below)


 Tree group with numbered reference.
Average canopy extent for group. BS5837:2012 tree quality category as shown below.

 Shrubs / Hedge with numbered reference.

BS 5837:2012 Tree Quality Categories - Table 1
 Category A - High quality
 Category B - Moderate quality
 Category C - Low quality
 Category U - Unsuitable for retention

 Root Protection Area (RPA) calculated in accordance with Section 4.6 - BS5837:2012

NOTES:
• Refer to RPS Tree Schedule for further details.
• Survey based on a visual inspection from the ground and is not intended as a full arboricultural inspection.
• Plan produced in accordance with recommendations set out in BS 5837:2012 - 'Trees in Relation to design, demolition and construction'.
• Due to the legal protection afforded to breeding birds vegetation removal should not take place during the bird nesting period; generally, although not restricted to, March - August inclusive.
• Survey carried out using sub metre GPS survey device and Topographical Survey information provided by Client.



P01	First issue		TF	DC	20.11.24
Rev	Description		By	Ckd	Date

rps MAKING COMPLEX EASY
A TETRA TECH COMPANY
Aurora House, Deltic Avenue, Rooksley,
Milton Keynes, MK13 8LD
United Kingdom
T: +44 1906 669 898 E: rpsmks@rpsgroup.com

Client **Surfacing Standards Limited**

Project **The Highfields School**

Title **Tree Constraints Plan**

Status	Scale	Date Created
For information	1:250 @A1	20.11.2024
Task Team Manager	Information Author	Task Information Manager
TF	TF	DC

Document Number
5297-RPS-XX-XX-DR-AR-9000
Project Code - Originator - Zone - Level - Type - Role - Drawing Number
RPS Project Number
794-PLN-LAN-5297
rpsgroup.com
Suitability
S3
Revision
P01