

Monitoring Details:

Level Monitoring

Provider Name: My Home Needs

Monitoring Interval: Every 8 weeks

Instruction Date: 09/09/2024

Number of Visits: 4

Reading Date: 13/01/2025

Visits Completed: 3

Date of Issue: 13/01/2025

Visits Outstanding: 1

Client Details:

Client: Crawfords

Engineer / Handler: -

Job Reference:


Monitored Address:

Address: 1 Colemans Close, Hitchin, SG5 3FJ

Front Elevation



Site Plan



Visit Notes

No visit notes have been entered for any visits

Level Readings

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	11/10/24	29/11/24	13/01/25					
D/C	9.8619	9.8600	9.8599					
TBM1	10.0000	10.0000	10.0000					
2	9.8408	9.8411	9.8403					
3	9.8460	9.8468	9.8462					
4	9.8420	9.8429	9.8425					
5	10.0805	10.0801	10.0800					
6	9.9246	9.9244	9.9243					
7	9.9284	9.9294	9.9288					
Taken by	TP	LD	TP					
Serial number	1212203	190	1212203					


Level Movement (Displayed in Millimeters)

	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	11/10/24	29/11/24	13/01/25					
D/C	0	-19	-2					
TBM1	0	0	0					
2	0	+0.3	-0.5					
3	0	+0.8	+0.2					
4	0	+0.9	+0.5					
5	0	-0.4	-0.5					
6	0	-0.2	-0.3					
7	0	+1	+0.4					


	Visit 1	Visit 2	Visit 3	Visit 4	Visit 5	Visit 6	Visit 7	Visit 8
	11/10/24	29/11/24	13/01/25					
8	9.9226	9.9234	9.9238					
9	10.4587	10.4589	10.4584					
10	10.0795	10.0807	10.0801					
Taken by	TP	LD	TP					
Serial number	1212203	190	1212203					

[illegible]

Level Readings Chart (Points D/C - 10)



Relative Movement (Relative Survey, for illustration purposes only)



10/10/2024

29/11/2024

13/01/2025