




Amendments

Issue No.	Date	Description
-	-	-
-	-	-

Plotting parameters

-40nT

(Negative values displace above the trace line. Hidden values have not been plotted)

100nT

50nT

0nT

Job No.

2404

Survey Date

NOV 2007

Client

CgMs CONSULTING LTD

Project Title

GEOPHYSICAL SURVEY- TILE KILN FARM, STEVENAGE

Subject

TRACE PLOT SHOWING NEGATIVE VALUES

STRATASCAN™

GEOPHYSICS FOR ARCHAEOLOGY AND ENGINEERING

VINEYARD HOUSE

UPPER HOOK ROAD

UPTON UPON SEVERN

UK

WR8 0SA

T: +44 (0)1684 592266

F: +44 (0)1684 594142

E: info@stratascan.co.uk

www.stratascan.co.uk

REGISTERED ORGANISATION IFA

Scale

1:1250

0m 10 20 30 40 50 60 70 80m

Plot

A1

Checked by

SAS

Issue No.

01

Date


NOV 07

Drawn by

RAJS

Figure No.

04



Amendments

Issue No.	Date	Description
-	-	-
-	-	-

Plotting parameters

Maximum +1nT (black)
Minimum -1nT (white)

-3SD

+3SD

+1nT

-1nT

Job No.

2404

Survey Date

OCT 2007

Client

CgMs CONSULTING LTD

Project Title

GEOPHYSICAL SURVEY- TILE KILN FARM, STEVENAGE

Subject

PROCESSED GRADIOMETER DATA

STRATASCAN™

GEOPHYSICS FOR ARCHAEOLOGY AND ENGINEERING

VINEYARD HOUSE
UPPER HOOK ROAD
UPTON UPON SEVERN
UK

WR8 0SA
T: +44 (0)1684 592266
F: +44 (0)1684 594142
E: info@stratascan.co.uk
www.stratascan.co.uk

0m1020304050607080m

1:1250

Plot

A1

Checked by

SAS

Issue No.

01

Date


NOV 07

Drawn by

RAJS

Figure No.

05



Amendments

Issue No.	Date	Description
-	-	-
-	-	-

KEY

- Discrete positive anomaly - possible pit
- Positive anomaly with associated negative response - ferrous object
- Magnetic disturbance - associated with pipe/cable
- Positive linear anomaly - cut feature of possible archaeological origin
- Negative linear anomaly- possible former bank/earthwork
- Linear anomaly likely yo be related to former field boundary
- Positive area anomaly - cut feature of possible archaeological origin
- Negative area anomaly- possible former bank/earthwork
- Spread of magnetic variation
- Magnetic disturbance- evidence of ground disturbance
- Area of magnetic disturbance- related to nearby metallic object
- Area of magnetic disturbance- related to made ground

Job No.

2404

Survey Date

OCT 2007

Client

CgMs CONSULTING LTD

Project Title

GEOPHYSICAL SURVEY- TILE KILN FARM, STEVENAGE

Subject

INTERPRETATION OF GRADIOMETER ANOMALIES

STRATASCAN™

GEOPHYSICS FOR ARCHAEOLOGY AND ENGINEERING

VINEYARD HOUSE

UPPER HOOK ROAD

UPTON UPON SEVERN

UK

WR8 0SA

T: +44 (0)1684 592266

F: +44 (0)1684 594142

E: info@stratascan.co.uk

www.stratascan.co.uk

IFA

Scale

1:1250

0m 10 20 30 40 50 60 70 80m

Plot

A1

Checked by

SAS

Issue No.

01

Date

NOV 07

Drawn by

RAJS

Figure No.

06