

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
29	17/03/25 - 20/03/25		
Description			
WS104			

Photo No.	Date		
30	17/03/25 - 20/03/25		
Description			
WS104 - Breakout pit			

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 31	Date 17/03/25 - 20/03/25		
Description WS104 - Made Ground			

Photo No. 32	Date 17/03/25 - 20/03/25	
Description WS104 - Reworked Chalk		

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 33	Date 17/03/25 - 20/03/25		
Description WS108 - Breakout pit			

Photo No.	Date	
34	17/03/25 - 20/03/25	
Description		
WS108 - Reworked Chalk		

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 35	Date 17/03/25 - 20/03/25		
Description WS108 Arisings			

Photo No. 36	Date 17/03/25 - 20/03/25	
Description WS109		

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
37	17/03/25 - 20/03/25		
Description			
WS109 - Made Ground			

Photo No.	Date		
38	17/03/25 - 20/03/25		
Description			
WS109 - Chalk			

Client: Letchworth Investment LLP	Site Location:	Project No.: 680199
---	-----------------------	-------------------------------


Photo No.	Date	
1	30/07/25 - 01/08/25	
Description		
WS201 Location		

Photo No.	Date	
2	30/07/25 - 01/08/25	
Description		
WS201 Arisings, right to left - 0.2m to 1.2m bgl		