

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
19	17/03/25 - 20/03/25		
Description CP103 - Type 1 Gravels			
Photo No.	Date		
20	17/03/25 - 20/03/25		
Description CP103 - Type 1 Gravels in situ			


Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
21	17/03/25 - 20/03/25		
Description Cobbles in CP103			

Photo No.	Date	
22	17/03/25 - 20/03/25	
Description CP104 Location		


Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 23	Date 17/03/25 - 20/03/25		
Description CP104 - Arisings at 1.00m bgl			

Photo No.	Date	
24	17/03/25 - 20/03/25	
Description		
CP104 - Arisings 13.00m bgl		

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 25	Date 17/03/25 - 20/03/25		
Description CP104 - Arisings at 15.30m bgl			

Photo No.	Date	
26	17/03/25 - 20/03/25	
Description		
CP104 - Arisings at 16.50m bgl		

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 27	Date 17/03/25 - 20/03/25		
Description WS102			

Photo No.	Date	
28	17/03/25 - 20/03/25	
Description		
WS103		