






Title:	Plot of Particle Size Distribution				Project:	Starwood House, Letchworth	
Figure No.:	6	Author:	HM	Date:	15/09/2025	Project No:	667884.0000.0000
Revision:	1	Checker:	HM	Date:	15/09/2025	Location:	Starwood House, Letchworth, SG6 2TS
						Client:	Letchworth Investment LLP





Title:		Plot of Plasticity by Geology				Project:		Starwood House, Letchworth		
						Project No.:		680199.0000.0000		
Figure No.:		7	Author:	JE	Date:	28/08/2025	Location:		Starwood House, Letchworth, SG6 2TS	
Revision:		A	Checker:	HM	Date:	15/09/2025	Client:		Letchworth Investment LLP	



Annex B: Site Photographs

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
1	17/03/25 - 20/03/25		
Description			
CP101 Location			

Photo No.	Date		
2	17/03/25 - 20/03/25		
Description			
CP101 - Arisings at 0.3m bgl			


Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
3	17/03/25 - 20/03/25		
Description CP101 - Arisings at 0.6m bgl			

Photo No.	Date		
4	17/03/25 - 20/03/25		
Description CP101 - Arisings at 1m bgl			

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
5	17/03/25 - 20/03/25		
Description CP101 - Chalk arisings between 2m and 10m bgl			

Photo No.	Date		
6	17/03/25 - 20/03/25		
Description CP101 - Arisings at 11m bgl			

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
7	17/03/25 - 20/03/25		
Description			
CP101 Installation			

Photo No.	Date		
8	17/03/25 - 20/03/25		
Description			
CP102 Location			