


Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 9	Date 17/03/25 - 20/03/25		
Description CP102 - Breakout pit			

Photo No.	Date	
10	17/03/25 - 20/03/25	
Description		
CP102 - Made Ground		

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
11	17/03/25 - 20/03/25		
Description CP102 - Reworked Chalk			

Photo No.	Date		
12	17/03/25 - 20/03/25		
Description CP102 - Arisings at 1.90m bgl			