

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 17	Date 17/03/25 - 20/03/25		
Description CP103 - Breakout pit			

Photo No.	Date	
18	17/03/25 - 20/03/25	
Description		
CP103 - Reworked Chalk		

Photograph Log

Client:		Site Location:		Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT		631621.0000.0001
Photo No.	Date			
19	17/03/25 - 20/03/25			
Description CP103 - Type 1 Gravels				
Photo No.	Date			
20	17/03/25 - 20/03/25			
Description CP103 - Type 1 Gravels in situ				