


Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
25	17/03/25 - 20/03/25		
Description CP104 - Arisings at 15.30m bgl			

Photo No.	Date		
26	17/03/25 - 20/03/25		
Description CP104 - Arisings at 16.50m bgl			

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 27	Date 17/03/25 - 20/03/25		
Description WS102			

Photo No.	Date	
28	17/03/25 - 20/03/25	
Description		
WS103		

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
29	17/03/25 - 20/03/25		
Description			
WS104			

Photo No.	Date	
30	17/03/25 - 20/03/25	
Description		
WS104 - Breakout pit		