

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 31	Date 17/03/25 - 20/03/25		
Description WS104 - Made Ground			

Photo No.	Date	
32	17/03/25 - 20/03/25	
Description		
WS104 - Reworked Chalk		

Photograph Log

Client: Letchworth Investment LLP		Site Location: Starwood House, Letchworth, SG6 2TT	Project No.: 631621.0000.0001
Photo No. 33	Date 17/03/25 - 20/03/25		
Description WS108 - Breakout pit			

Photo No.	Date	
34	17/03/25 - 20/03/25	
Description		
WS108 - Reworked Chalk		

Photograph Log

Client:		Site Location:	Project No.:
Letchworth Investment LLP		Starwood House, Letchworth, SG6 2TT	631621.0000.0001
Photo No.	Date		
35	17/03/25 - 20/03/25		
Description			
WS108 Arisings			

Photo No.	Date		
36	17/03/25 - 20/03/25		
Description			
WS109			