

Existing Site Plan



Indicative Boundary Diagram



Site Photo A

Existing wire and post boundary fence and abutting timber fence installed within the grounds of No. 2 Cloisters Lawn.



Site Photo B

Existing wire and post boundary fence between residential properties and St Christopher school with hedge planted within school grounds.



Site Photo C

Existing space between wire and post boundary fence and hedge.

St Christopher School

Site Photos