52 North Avenue, Letchworth Garden City

Photograph 1 – Proposed dormer window location and position photographs have been taken from.



Photograph 2 – View from proposed dormer window position. Note tree between conservatory and hedge.



52 North Avenue, Letchworth Garden City

Photograph 3 – General of rear gardens indicating trees at No 50 which provide screening when in leaf and overlooking from 77 Norton Road.



Photograph 4 – General view of flat roof extension and conservatory at No 50

